

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011746/EVY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00121902101
<b>Claimant Vehicle No :</b>	SJS3879T	<b>Insured Vehicle No :</b>	GBG7411R
Date of Loss:	11/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206483/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJS3879T</b>	Engine No:	27294531086250
Make & Model:	MERCEDES-BENZ R280L, 3.0 (A)	Chassis No:	WDC2511542A098796
Reg. Date:	14/08/2009 (Man. Year: 2009)	Odometer:	243521 km
Colour:	Black		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	255/55Z R18	Rear Tyre Size:	255/55Z R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,165.50	2,856.50	6,309.00	68.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,070.00	550.00	33.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,785.50</b>	<b>3,926.50</b>	<b>6,859.00</b>	<b>63.59</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,100.00</b>		
<b>(\$\$)</b>	10,785.50	3,100.00	7,685.50	71.26
<b>+ GST 7.00/7.00% (\$\$)</b>	754.99	217.00	537.99	71.26
<b>Nett Amount (\$\$)</b>	<b>11,540.49</b>	<b>3,317.00</b>	<b>8,223.49</b>	<b>71.26</b>

**INSPECTION**

Date of Assignment:	27/12/2021	
Date Inspected:	18/11/2021	Inspected At:
Estimated Period of Repair:	4.0 days	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Mar 2022)
<b>Parts:</b>	M1-SUV	MERCEDES-BENZ R280L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJS3879T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Not Necessary	1,250.00 FL	*- FL
2	1		*PARK LAMP RH	Broken	120.00 FL	*120.00 FL
3	1		*FRONT BUMPER	Repair	2,150.00 FL	*- FL
4	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	290.00 FL	*- FL
5	1		*FRONT BUMPER INNER BOX	Not Necessary	310.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE CENTRE	Not Necessary	280.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,180.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER LH /RH	Not Necessary	130.00 FL	*- FL
9	10		*FRONT BUMPER RIVETS	Necessary	70.00 FL	*30.00 FL
10	2		*PARKING SENSOR CENTRE LH/RH	Not Necessary	410.00 FL	*- FL
11	6		*PARKING SENSOR RING	Necessary	42.00 FL	*42.00 FL
12	1		*REAR BUMPER	Crushed	1,800.00 FL	*1,800.00 FL
13	1		*REAR BUMPER LOWER GARNISH	Cut	680.00 FL	*680.00 FL
14	1		*REAR BUMPER TOP PLATE	Dented	405.00 FL	*405.00 FL
15	2		*REAR BUMPER SIDE RETAINER LH /RH	Not Necessary	80.00 FL	*- FL
16	10		*REAR BUMPER RIVETS	Necessary	70.00 FL	*30.00 FL
17	2		*REVERSE SENSOR CENTRE LH & RH	Not Necessary	410.00 FL	*- FL
18	4		*REVERSE SENSOR RING	Necessary	28.00 FL	*28.00 FL
19	1		*REAR BUMPER SUPPORT	Not Necessary	440.00 FL	*- FL
20	1		*NUMBER PLATE	Broken	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,180.00</b>	<b>3,170.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,014.50	313.50
<b>Total Parts (\$\$)</b>	<b>9,165.50</b>	<b>2,856.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	40.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	120.00	60.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
4	TO DISMANTLE ALL DAMAGED PARTS TO KNOCK & REPAIR REAR END PANEL,INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	700.00	500.00
5	TO SPRAY FRONT BUMPER ,REAR BUMPER ,REAR END PANEL	New	700.00	440.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,620.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >