

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21011750/RPA3Q2**Date:** 10/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900087839
Claimant Vehicle No :	SMB1649H	Insured Vehicle No :	SMK4903G
Date of Loss:	23/10/2021	Nature of Claim:	TP
		Claim No:	1738477717SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1649H	Engine No:	50339770013972
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Chassis No:	WMAA22ZZ7F7002651
Reg. Date:	27/02/2015 (Man. Year: 2014)	Odometer:	501909 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,141.70	1,027.53	114.17	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,503.00	976.00	527.00	35.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,644.70	2,003.53	641.17	24.24
Approved Total (Overridden) (\$\$)		1,800.00		
Nett Amount (\$\$)	2,644.70	1,800.00	844.70	31.94
+ Loss of Use (2.5 x S\$250.00/day) (\$\$)		625.00		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		2,432.00		

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	15/11/2021	Inspected At:
Estimated Period of Repair:	2.0 days	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ,STOP :LED (MAN BUS)	Cracked	1,141.70 F	*1,141.70 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					1,141.70	1,141.70
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	114.17
Total Parts (\$)					1,141.70	1,027.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	708.00	446.00
Gross Labour Cost (\$\$)			1,503.00	976.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >