



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304903

INV Date 01/08/2023

Reference CC4/LPC21011752/Eya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKX 6121M
Insured Veh. GBD 7180Y
Claim No. 21/21/21/VC00/025162
Policy No. Z/21/VC00/110456
Accident Date 16/11/2021
Inspection Date 18/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21011752/Eya3q2 Date: 01/08/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 7180Y	Veh. Inspected	SKX 6121M	
Policy No.	Z/21/VC00/110456	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025162	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	17/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA2E32020P836843	Colour	WHITE	
Odometer	80964 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	MICHELIN	5 mm	
L/H Front Tyre	225/45 R18	MICHELIN	5 mm	
R/H Rear Tyre	225/45 R18	MICHELIN	5 mm	
L/H Rear Tyre	225/45 R18	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2021	Inspection Date	18/11/2021	
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 6121M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (WCP)	BROKEN	750.00	750.00
1	REAR BUMPER TOW COVER (WCP)	NOT NECESSARY	45.00	-
1	RH REAR BUMPER RETAINER (WCP)	BROKEN	95.00	95.00
1	RH REAR BUMPER REFLECTOR (WCP)	BROKEN	45.00	45.00
1	RH REAR BUMPER OUTER PARKING SENSOR (WCP)	NOT NECESSARY	230.00	-
1	REAR BUMPER CHROME MOULDING (WCP)	NOT NECESSARY	120.00	-
1	RH REAR BUMPER INNER BRACKET (WCP)	BROKEN	110.00	110.00
1	RH OUTER TAIL LAMP (WCP)	BROKEN	380.00	380.00
1	RH OUTER TAIL LAMP INNER PANEL (WCP)	DENTED	950.00	950.00
1	REAR WINDSCREEN (WCP)	NOT NECESSARY	680.00	-
1	REAR TAILGATE TOP SPOILER (WCP)	BROKEN	420.00	420.00
1	RH REAR TAILGATE TOP SPOILER BRACKET (WCP)	BROKEN	280.00	280.00
1	RH REAR TAILGATE INNER TAIL LAMP (WCP)	BROKEN	210.00	210.00
1	RH REAR TAILGATE WINDSCREEN BLACK MOULDING (WCP)	MISSING	85.00	85.00
1	REAR TAILGATE EMBLEM (WCP)	NECESSARY	70.00	70.00
	COST PLUS 15%		670.50	509.25
			5,140.50	3,904.25
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR WINDSCREEN INNER RUBBER SEAL (SN)	NECESSARY	28.00	28.00
			88.00	68.00
<u>LABOUR</u>				
	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST.		120.00	120.00
	TO INSTALL REAR WINDSCREEN SOLAR WINDSCREEN.	NOT NECESSARY	250.00	-
	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL,REAR FLOOR PANEL,RH REAR FENDER PANEL,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE DAMAGED PARTS AND ADJUST REAR BODY AND TAILGATE ALIGNMENT.		680.00	600.00

Report Ref No. CC4/LPC21011752/Eya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY.		850.00	800.00
	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY.		25.00	20.00
	TO PERFORM COMPUTER DIAGNOSTIC ON PARKING SYSTEM ,REAR TAILGATE CONTROLS AND CLEAR FAULT CODES.		150.00	100.00
			2,075.00	1,640.00
GRAND TOTAL			7,303.50	5,612.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/LPC21011752/Eya3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 6121M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 6121M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKX 6121M

RE-INSPECTION

