

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5336T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL SUB-ASSY,REAR DOOR,RH (DISC 25%)	BENT	1,294.90	971.18
1	PANEL SUB-ASSY,FENDER REAR RH (DISC 25%)	BENT	871.50	653.63
1	CAP SUB-ASSY,WHEEL (DISC 25%)	SCRATCHED	211.50	158.63
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	COVER,RR BUMPER ASSY	NOT NECESSARY	332.70	-
1	PIXEL STICKER	NOT NECESSARY	60.00	-
1	CHECK ASSY,REAR DOOR	NOT NECESSARY	183.80	-
1	HINGE ASSY,REAR DOOR,UPPER RH	NOT NECESSARY	98.90	-
1	HINGE ASSY,REAR DOOR,LOWER RH	NOT NECESSARY	87.10	-
1	DOOR REAR MOTOR ASSY,POWER WINDOW	NOT NECESSARY	926.00	-
1	DOOR REAR WINDOW REGULATOR SUB-ASSY,RH	NOT NECESSARY	206.70	-
1	LINER REAR FENDER,RH	NOT NECESSARY	139.80	-
1	WHEEL,DISC	NOT NECESSARY	1,879.40	-
1	TYRE	NOT NECESSARY	126.74	-
1	HUB & BEARING ASSY,RH & LH	NOT NECESSARY	668.90	-
1	MOULDING ASSY,BODY ROCKER PANEL,RH	TO REPAIR SEE LABOUR	594.80	-
			7,742.74	1,843.44
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF MOULDING ASSY,BODY ROCKER PANEL,RH.		676.00	600.00
	SPRAY PAINT.		1,494.00	500.00
	TO DO WHEEL ALIGNMENT/TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO TRANSFER DOOR MECHANISM.		120.00	60.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	60.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-

Report Ref No. NS/INC21011759/R1qcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,870.00	1,220.00
	GRAND TOTAL		10,612.74	3,063.44

RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,063.44
---	--	--	----------

Report Ref No. NS/INC21011759/R1qcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser