

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011761/AVCE2**Date:** 03/01/2022**REFERENCE**

Insured/Claimant:	TADOKORO DAI	Policy No:	7210063244	
Date of Loss:	11/11/2021	Nature of Claim:	OD	Claim No: 0869246868SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA5120H		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC38056
Reg. Date:	25/06/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF37M1107305
Colour:	Bronze	Odometer:	2316 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$176,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,533.00	3,367.36	9,165.64	73.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,252.00	2,122.00	11,130.00	83.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,785.00	5,489.36	20,295.64	78.71
- Excess (\$\$)	3,800.00	3,800.00	0.00	0.00
(\$\$)	21,985.00	1,689.36	20,295.64	92.32
+ GST 7.00/7.00% (\$\$)	1,538.95	118.26	1,420.69	92.32
Nett Amount (\$\$)	23,523.95	1,807.62	21,716.33	92.32

INSPECTION

Date of Assignment:	18/11/2021	
Date Inspected:	17/11/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	2,816.00 FS	*2,252.80 FS
2	1		*REAR DOOR OUTER SEAL - RH	Necessary	135.00 FS	*108.00 FS
3	1		*REAR DOOR CATCH - RH	Not Necessary	120.00 FS	*- FS
4	1		*REAR DOOR SILL PANEL - RH	Not Necessary	135.00 FS	*- FS
5	1		*REAR DOOR COVER - RH	Distorted	349.00 FS	*279.20 FS
6	1		*REAR DOOR INNER SEAL - RH	Not Necessary	191.00 FS	*- FS
7	1		*REAR WINDOW REGULATOR - RH	Not Necessary	282.00 FS	*- FS
8	1		*REAR WINDOW REGULATOR MOTOR - RH	Not Necessary	271.00 FS	*- FS
9	1		*FRONT DOOR CONTROL UNIT - RH	Not Necessary	400.00 FS	*- FS
10	1		*FRONT SECTIONAL PART PILLAR A/B - RH	Not Necessary	3,470.00 FS	*- FS
11	1		*SILL TRIM STRIP - RH	Not Necessary	556.00 FS	*- FS
12	1		*FRONT SIDE TRIM - RH	Not Necessary	179.00 FS	*- FS
13	1		*FRONT DOOR COVER - RH	Cut	370.00 FS	*296.00 FS
14	1		*REAR WHEEL ARCH TRIM - RH	Cut	536.00 FS	*428.80 FS
15	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	241.00 FS	*- FS
16	1		*REAR WHEEL SPOILER - RH	Not Necessary	40.00 FS	*- FS
17	1		*REAR ALUMINIUM RIM - RH	Not Necessary	1,262.00 FS	*- FS
18	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
19	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
20	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
21	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
22	1		*SUNDRIES	Necessary	400.00 FS	*2.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	12,533.00	3,367.36
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER MODULE WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
2	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY RHS FRONT DOOR	New	280.00	0.00
3	TO REMOVE AND REINSTALL FRONT SEAT ASSY, REAR SAT ASS, BACK REST, ABCD PILLAR TRIMS, CARPETS, ELECTRICAL COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
4	TO DISMANTLE AND RENEW RHS REAR DOOR. TO CUT OUT AND WELD RHS SILL PANEL AND RHS B-PILLAR, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	500.00
5	TO RESPRAY RHS REAR DOOR, RHS REAR DOOR COVER, RHS FRONT DOOR, RHS FRONT DOOR COVER, RHS REAR WHEEL ARCH TRIMS, RHS SILL PANEL, RHS B-PILLAR AND DOOR ENTRANCE	New	5,500.00	1,150.00
6	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			13,252.00	2,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >