

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 1882A

| Qty | Description of Parts                    | Condition     | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|----------------------------|-------------------|
|     | REPLACEMENT OF PARTS                    |               |                            |                   |
| 1   | FRONT BUMPER                            | DISTORTED     | 1,082.40                   | 1,082.40          |
| 1   | FRONT BUMPER LOGO                       | NECESSARY     | 45.60                      | 45.60             |
| 1   | FRONT BUMPER SIDE HOLDER LH             | DAMAGED       | 37.80                      | 37.80             |
| 1   | FRONT BUMPER FOG LAMP LH                | NOT NECESSARY | 340.20                     | -                 |
| 1   | FRONT BUMPER FOG LAMP COVER LH          | DEFORMED      | 79.40                      | 79.40             |
| 1   | FRONT BUMPER REINFORCEMENT              | NOT NECESSARY | 506.20                     | -                 |
| 1   | FRONT BUMPER SPONGE                     | NOT NECESSARY | 130.60                     | -                 |
| 1   | FRONT LH FENDER                         | DISTORTED     | 430.90                     | 430.90            |
| 1   | FRONT LH FENDER INNER SHIELD            | DEFORMED      | 145.10                     | 145.10            |
| 1   | FRONT LH FENDER BRACKET                 | BENT          | 35.90                      | 35.90             |
| 1   | FRONT LH LOWER ARM                      | BENT          | 389.30                     | 389.30            |
| 1   | FRONT LH SHOCK ABSORBER                 | BENT          | 275.40                     | 275.40            |
| 1   | FRONT LH KNUCKLE ARM                    | DAMAGED       | 368.40                     | 368.40            |
| 1   | FRONT LH WHEEL HUB C/W BEARING          | DAMAGED       | 159.90                     | 159.90            |
| 1   | FRONT LH DRIVE SHAFT                    | NOT NECESSARY | 1,265.40                   | -                 |
|     | LESS 20% DISCOUNT                       |               | -                          | -610.02           |
|     |   |               | 5,292.50                   | 2,440.08          |
|     | SPECIAL NETT ITEMS                      |               |                            |                   |
| 1   | FRONT BUMPER CLIPS (SN)                 | NECESSARY     | 30.00                      | 30.00             |
| 1   | FRONT LH FENDER INNER SHIELD CLIPS (SN) | NECESSARY     | 30.00                      | 30.00             |
| 1   | FRONT LH WHEEL RIM (SN)                 | CUT           | 800.00                     | 500.00            |
| 1   | FRONT LH TYRE (SN)                      | CUT           | 300.00                     | 180.00            |
|     |   |               | 1,160.00                   | 740.00            |
|     | <u>LABOUR</u>                           |               |                            |                   |
|     | PANEL BEATING.                          |               | 800.00                     | 500.00            |
|     | SPRAY PAINTING.                         |               | 800.00                     | 400.00            |
|     | WIRING.                                 |               | 50.00                      | 30.00             |
|     | TO SPRAY TUFF COAT.                     |               | 150.00                     | 40.00             |
|     | TO DISMANTLE FRONT UNDERCARRIAGE.       |               | 350.00                     | 200.00            |
|     | TO PERFORM WHEEL ALIGNMENT.             |               | 150.00                     | 80.00             |

Report Ref No. CS/SMO21011765/Atf3n2



## **LKK Auto Consultants Pte Ltd**

Page No.:2 of 2

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Qty | Description of Parts | Condition | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------|-----------|-------------------------------|-------------------|
|     | TOWING FEES.         |           | 60.00                         | 60.00             |
|     |                      |           | 2,360.00                      | 1,310.00          |
|     | GRAND TOTAL          |           | 8,812.50                      | 4,490.08          |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 3,600.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |          |

Report Ref No. CS/SMO21011765/Atf3n2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.