

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21011766/EUF3E2

Date: 02/12/2021

REFERENCE

Insured/Claimant:	TAN SENG HOE	Policy No:	2070036100		
Date of Loss:	17/11/2021	Nature of Claim:	OD	Claim No:	3869090800SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF1991H		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11BN0171
Reg. Date:	13/03/2020 (Man. Year: 2019)	Chassis No:	GF7W0602175
Colour:	Red	Odometer:	37969 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 4 mm	Rear Left Side:	Toyo 4 mm
Front Right Side:	Toyo 4 mm	Rear Right Side:	Toyo 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,209.51	2,506.28	1,703.23	40.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,510.00	450.00	22.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,169.51	4,016.28	2,153.23	34.90
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,569.51	3,416.28	2,153.23	38.66
+ GST 7.00/7.00% (S\$)	389.87	239.14	150.73	38.66
Nett Amount (S\$)	5,959.38	3,655.42	2,303.96	38.66

INSPECTION

Date of Assignment:	18/11/2021	
Date Inspected:	19/11/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
3	1		*HEADLAMP ASSY, RH	Not Necessary	1,948.00 FL	*- FL
4	2		*GARNISH, FR BUMPER, RH	Not Necessary	96.00 FL	*- FL
5	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 FL	*- FL
6	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	18.00 FL	*- FL
7	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
8	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
9	1		*REINFORCEMENT, FR BUMPER	Bent	493.00 FL	*493.00 FL
10	2		*REINFORCEMENT FR BMPR SIDE	Not Necessary	44.00 FL	*- FL
11	1		*FACE, FR BUMPER	Crushed	851.00 FL	*851.00 FL
12	1		*EXTENSION, FR BUMPER	Cut	517.00 FL	*517.00 FL
13	1		*COVER, FR BUMPER	Cut	361.00 FL	*361.00 FL
14	1		*GRILLE ASSY RADIATOR	Cut	550.00 FL	*550.00 FL
15	1		*COVER, FR BUMPER	Not Necessary	25.00 FL	*- FL
16	1		*COVER, HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
17	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL
18	10		*CLIPS (Supplementary)	Necessary	40.00 FL	*40.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,443.00	3,234.00
- List Item Discount on L Items 23.00/23.00% (S\$)	1,233.49	727.72
Total Parts (S\$)	4,209.51	2,506.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE ON FRT BUMPER CENTER GRILLE, FRT BUMPER LWR & AFFECTED AREA. REPAIR ON FRT BUMPER PANEL	New	900.00	450.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	REMOVE & REPLACE FRT PARKING ASSIST	New	80.00	80.00
4	TO SUPPLY FRT PARKING ASSIST	New	480.00	480.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (S\$)			1,960.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >