



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>KCV15539/TAN SENG HOE</td></tr> <tr> <td>Reg No/Reg Date</td><td>SJF1991H / 13/03/202</td></tr> <tr> <td>Date In/Mileage</td><td>19/11/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0602175</td></tr> <tr> <td>Engine No</td><td>4J11BN0171</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr> <td>Colour/Trim</td><td>P02 RED METALLIC / BK BLACK</td></tr> </table>	Cust No/Name	KCV15539/TAN SENG HOE	Reg No/Reg Date	SJF1991H / 13/03/202	Date In/Mileage	19/11/2021/ 0	Chassis No	GF7W0602175	Engine No	4J11BN0171	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	P02 RED METALLIC / BK BLACK
Cust No/Name	KCV15539/TAN SENG HOE														
Reg No/Reg Date	SJF1991H / 13/03/202														
Date In/Mileage	19/11/2021/ 0														
Chassis No	GF7W0602175														
Engine No	4J11BN0171														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	P02 RED METALLIC / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/11/2021/ 11:19	BLK	282 / Kevin Leong	17687
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	1				900.00
REPLACE ON FRT BUMPER CENTER GRILLE, FRT BUMPER LWR & AFFECTED AREA	450 x 1	450			450
REPAIR ON FRT BUMPER PANEL					350.00
E PNT98000	1				80.00
PAINT WORK ON FRT BUMPER PANEL	350 x 1				80.00
E PNT88000					220.00
REMOVE & REPLACE FRT PARKING ASSIST	BR				480
M SUNDRY					30.00
TO SUPPLY FRT PARKING ASSIST					30.00
A 54900099					120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					50.00
A 10028901					30.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					30.00
M SUNDRY					30.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME					30.00
M SUNDRY					30.00
SUNDRIES					30.00
M HEADLAMP ASSY,RH	? x nn	1.00	1948.00	23.00	1499.96
P GARNISH,FR BUMPER,RH	? x nn	2.00	48.00	23.00	73.92
M BRACKET,FR BUMPER SIDE,RH	? x nn	1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,LH	? x nn	1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER SIDE	(chrome) - BR (RH)	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	(chrome) - BR (RH)	1.00	112.00	23.00	86.24
M REINFORCEMENT,FR BUMPER	- BT	1.00	493.00	23.00	379.61
M REINFORCEMENT,FR BMPR SIDE	- X nn	2.00	22.00	23.00	33.88
M FACE,FR BUMPER	- CRU	1.00	851.00	23.00	655.27
M EXTENSION,FR BUMPER	- CUT (silver)	1.00	517.00	23.00	398.09
M COVER,FR BUMPER	- CUT (black)	1.00	361.00	23.00	277.97
M GRILLE ASSY,RADIATOR	- CUT	1.00	550.00	23.00	423.50
M COVER,FR BUMPER	- X nn	1.00	25.00	23.00	19.25
M COVER,HEADLAMP SUPT PANEL	? x nn	1.00	50.00	23.00	38.50

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "WIP" basis

Authorized signatory and company stamp

Nett 5,863.31

3 days 7% GST on 5863.31 410.43

Total Payable 6,273.74

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.