



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 276J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	80.60	80.60
1	TAILGATE	DENTED	1,466.20	1,466.20
1	TAILGATE REAR LOGO	NECESSARY	58.00	58.00
1	TAILGATE INNER LOCK	SHORTED / DAMAGED	241.20	241.20
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	155.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	285.00	-
1	REAR BUMPER	DENTED	1,200.00	886.00
1	REAR BUMPER LOWER GARNISH	GRAZED	305.00	305.00
1	REAR BUMPER BEAM	DENTED	485.00	485.00
2	REAR BUMPER SIDE RETAINERS @\$45.00	NOT NECESSARY	90.00	-
1	REAR END PANEL	DENTED	508.00	508.00
1	REAR END PANEL TOP GARNISH	CRACKED	166.00	166.00
1	REAR END PANEL AIR VENT	DEFORMED	68.00	68.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR FENDER OUTER GARNISH N/S	TORN	185.00	185.00
1	TAILLAMP N/S	CRACKED	320.00	320.00
	LESS 10% DISCOUNT		-686.30	-476.90
			6,176.70	4,292.10
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			430.00	330.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00

Report Ref No. CS/SMO21011772/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.		80.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		900.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	800.00
			2,560.00	1,790.00
GRAND TOTAL			9,166.70	6,412.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CS/SMO21011772/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.