

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011773/DTY3Q2**Date:** 14/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00093592100

Claimant Vehicle No : SMF6234S **Insured Vehicle No :** SLA28Z

Date of Loss: 17/11/2021 Nature of Claim: TP Claim No: SNM21D206625/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF6234S**

Make & Model: MITSUBISHI LANCER, 1.3 (A) Engine No: 4A92CD1247

Reg. Date: 13/01/2016 (Man. Year: 2015) Chassis No: JMYSRCY1AFU005740

Colour: White Odometer: 152363 km

Engine Capacity: 1590 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,765.78	13,889.50	37,876.28	73.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,750.00	3,270.00	8,480.00	72.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	63,515.78	17,159.50	46,356.28	72.98
Approved Total (Overridden) (\$\$)		12,000.00		
Nett Amount (\$\$)	63,515.78	12,000.00	51,515.78	81.11

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 18/11/2021 Inspected At: C S Ong Motor (HQ)
BLK 10 ANG MO KIO IND PARK 2A #04-01 AMK
AUTO POINT
Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2022)
Parts:	143	MITSUBISHI LANCER 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF6234S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BONNET HINGE LH/RH	Repair	140.00 FL	*- FL
2	1		*BONNET LOCK	Bent	160.00 FL	*160.00 FL
3	1		*BONNET STRIKER LOCK	Not fitted	88.00 FL	*- FL
4	1		*BONNET SEAL	Not fitted	58.00 FL	*- FL
5	2		*HEAD LAMP LH /RH	Mtg Broken	3,796.00 FL	*1,702.00 FL
6	2		*HEAD LAMP LOWER BRACKET LH/RH	Repair	160.00 FL	*- FL
7	2		*HEAD LAMP PANEL LH /RH	Repair	356.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	140.00 FL	*- FL
9	1		*FRONT BUMPER NO PLATE BASE	Cracked / Broken	240.00 FL	*138.00 FL
10	1		*FRONT REINFORCEMENT BAR	Dented	1,026.00 FL	*390.00 FL
11	1		*FRONT SUPPORT PANEL	Dented / Bent	1,767.00 FL	*582.00 FL
12	1		*HORN	Serviceable	65.00 FL	*- FL
13	1		*A/C CONDENSOR ASSY	Bent	1,721.00 FL	*1,016.00 FL
14	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	356.00 FL	*- FL
15	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	312.00 FL	*- FL
16	1		*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	692.00 FL	*- FL
17	1		*RADIATOR ASSY	Bent	2,061.00 FL	*1,161.00 FL
18	1		*RADIATOR TOP HOSE	Not Necessary	49.00 FL	*- FL
19	1		*RADIATOR BOTTOM HOSE	Not Necessary	64.00 FL	*- FL
20	1		*RADIATOR FAN MOTOR	Not Necessary	422.00 FL	*- FL
21	1		*RADIATOR FAN BLADE	Not Necessary	268.00 FL	*- FL
22	1		*RADIATOR FAN COWLING	Cracked	443.00 FL	*250.00 FL
23	1		*BOOTLID	Buckled	1,893.00 FL	*899.00 FL
24	1		*BOOTLID LOGO	Necessary	121.20 FL	*57.00 FL
25	1		*BOOTLID INNER TRIM	Bent	983.00 FL	*181.00 FL
26	2		*BOOTLID HINGE LH/RH	Repair	248.00 FL	*- FL
27	2		*BOOTLID LAMP LH/RH	Serviceable	1,348.00 FL	*- FL
28	1		*BOOTLID BRAKE LAMP	Not Necessary	536.00 FL	*- FL
29	1		*BOOTLID WEATHERSTRIP	Deformed	366.00 FL	*166.50 FL
30	1		*BOOTLID LOCK	Damaged	367.00 FL	*159.00 FL
31	1		*BOOTLID STRIKER LOCK	Repair	97.00 FL	*- FL
32	1		*SET BOOTLID STOPPERS	Serviceable	50.00 FL	*- FL
33	2		*TAIL LAMP LH/RH	Cracked	2,064.00 FL	*712.00 FL
34	2		*TAIL LAMP PANEL LH/RH	Dented	556.00 FL	*358.00 FL
35	2		*TAIL LAMP LOWER BRACKET LH/RH	Serviceable	396.00 FL	*- FL
36	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	150.00 FL	*- FL
37	1		*REAR BUMPER REFLECTOR LH/RH	O/S Serviceable / N/S	184.00 FL	*92.00 FL
38	2		*REAR BUMPER BRACKET LH/RH	Cracked		
39	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	300.00 FL	*- FL
40	1		*REAR REINFORCEMENT BAR	Damaged	95.00 FL	*56.80 FL
41	1		*REAR END PANEL	Dented	982.00 FL	*256.00 FL
42	1		*REAR END PANEL TOP GARNISH	Buckled	1,806.00 FL	*506.00 FL
43	1		*SPARE WHEEL PANEL	Deformed	349.00 FL	*166.70 FL
44	2		*SPARE WHEEL QUARTER PANEL LH/RH	Dented	1,921.00 FL	*845.00 FL
				Repair	1,152.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SPARE WHEEL PANEL TOP BOARD	Cracked / Bent	655.00 FL	*167.00 FL
46	2		*REAR FENDER LH /RH	Repair	4,196.00 FL	*- FL
47	2		*REAR FENDER INNER TRIM BOARD LH/RH	Torn	1,882.00 FL	*784.00 FL
48	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	179.00 FL	*- FL
49	1		*REAR EXHAUST MOUNTIGN	Not Necessary	120.00 FL	*- FL
50	1		*REAR EXHAUST MID PIPE	Not Necessary	1,935.00 FL	*- FL
51	1		*REAR EXHAUST MID PIPE MOUNTING	Not Necessary	120.00 FL	*- FL
52	1		*REAR WINDSCREEN MOULDING	Not Necessary	349.00 FL	*- FL
53	1		*BONNET	Dented	2,400.00 FS	*850.00 FS
54	1		*FRONT BUMPER	Dented	2,000.00 FS	*800.00 FS
55	1		*FRONT BUMPER LOWER LID	Cracked	1,800.00 FS	*350.00 FS
56	1		*FRONT BUMPER SIDE GRILLE	Serviceable	800.00 FS	*- FS
57	1		*FRONT BUMPER GRILLE	Broken	1,000.00 FS	*400.00 FS
58	1		*FRONT BUMPER LOWER GRILLE	Mtg Cracked	800.00 FS	*250.00 FS
59	1		*REAR BUMPER	Dented	2,000.00 FS	*850.00 FS
60	1		*REAR EXHAUST PIPE	Repair	3,000.00 FS	*- FS
61	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
63	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
64	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
65	1		*REAR BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*COOLANT	Not Necessary	100.00 FS	*- FS
67	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
68	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
69	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
70	1		*SPARE WHEEL PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
71	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
72	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
73	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
74	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
75	1		*FRONT & REAR NO PLATE & CASING	Bent / Missing	200.00 FS	*90.00 FS
76	1		*SET REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
77	1		*REVERSE CAMERA	Damaged	600.00 FS	*250.00 FS
78	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
79	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	55,744.20	14,970.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,978.42	1,080.50
Total Parts (\$\$)	51,765.78	13,889.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	400.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,400.00	1,000.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,400.00	800.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSER & REFILL GAS TO FACILITATE REPAIRS	New	200.00	80.00
8	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	50.00
9	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
11	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	0.00
12	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	60.00
13	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	400.00	30.00
14	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
15	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			11,750.00	3,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >