

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21011775/VQF3E2

**Date:** 25/11/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900017303  
**Claimant Vehicle No :** SLT4267Z **Insured Vehicle No :** SMJ1769C  
Date of Loss: 16/11/2021 Nature of Claim: TP Claim No: 2459115250SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT4267Z**  
Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5568922  
Reg. Date: 27/10/2017 (Man. Year: 2017) Chassis No: GB71040464  
Colour: Red Odometer: 120040 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 18/11/2021  
Date Inspected: 23/11/2021 Inspected At: Teamwork Garage Pte Ltd (HQ)  
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park  
Singapore 408934  
Estimated Period of Repair: 4.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$74,000.00 (EST)

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Dented	0.00 F	*- F
2	1		*FRT LH DOOR STICKER	Necessary	0.00 F	*- F
3	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
4	1		*REAR LH DOOR	Dented	0.00 F	*- F
5	1		*REAR LH DOOR STICKER	Necessary	0.00 F	*- F
6	1		*REAR LH FENDER	Repair	0.00 F	*- F
7	1		*RIM LH REAR	Scratched	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >