

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG121011777/EVF3E2

Date: 14/07/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK8390X

Insured Vehicle No : YG99H

Date of Loss: 13/10/2021

Nature of Claim: TP

Claim No: CDMCG21001985

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK8390X**

Make & Model: MAZDA 6, 2.0 (A)

Engine No: PE21601182

Reg. Date: 11/08/2021 (Man. Year: 2021)

Chassis No: JM6GL1073M0454732

Colour: Black

Odometer: 16955 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,612.70	1,423.20	1,189.50	45.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	2,070.00	3,010.00	59.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,692.70	3,493.20	4,199.50	54.59
+ GST 7.00/7.00% (S\$)	538.49	244.52	293.97	54.59
Nett Amount (S\$)	8,231.19	3,737.72	4,493.47	54.59

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 27/04/2022

Inspected At:

27A Tanjong Penjuru

Repairer: Trans Eurokars Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2022)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK8390X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,099.00 F	*1,099.00 F
2	4		*TAPE PROTECTOR	Necessary	18.80 F	*18.80 F
3	2		*RETAINER S.S ULTRASONIC CENTER	Not Necessary	33.60 F	*- F
4	2		*SENSOR, ULTRASONIC CENTER	Not Necessary	378.00 F	*- F
5	2		*TAPE SEAL	Necessary	27.40 F	*27.40 F
6	4		*GROMMET, SCREW	Necessary	10.80 F	*10.80 F
7	1		*BRACKET CENTER REAR BUMPER	Not Necessary	5.40 F	*- F
8	1		*REINFORCEMENT REAR	Not Necessary	538.30 F	*- F
9	1		*COVER, UNDER-RR	Not Necessary	122.20 F	*- F
10	2		*RIVET	Necessary	18.40 F	*18.40 F
11	6		*RIVET	Necessary	48.00 F	*48.00 F
12	1		*COVER TOWING LH REAR	Missing	46.60 F	*46.60 F
13	1		*COVER TOWING RH REAR	Missing	46.60 F	*46.60 F
14	1		*RETAINER LH REAR	Not Necessary	41.00 F	*- F
15	1		*RETAINER RH REAR	Not Necessary	41.00 F	*- F
16	1		*GASKET TAIL LAMP RH	Necessary	43.80 F	*43.80 F
17	1		*GASKET TAIL LAMP LH	Necessary	43.80 F	*43.80 F
18	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,612.70	1,423.20
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER	New	1,980.00	660.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,890.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	200.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	250.00
Gross Labour Cost (\$)			5,080.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >