2/14/22, 12:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21011778/RGA3Q2

Date: 14/02/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_01

Claimant Vehicle SLL4534U Insured Vehicle No: SMR9628G

Date of Loss: 13/11/2021 Nature of Claim: TP Claim No: MFL2021D0004930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL4534U

Make & Model: VOLKSWAGEN SPORTSVAN, 1.4 (A) Engine No: CZC069164

Reg. Date: 27/02/2017 (Man. Year: 2015) Chassis No: WVWZZZAUZGW533482

Colour: White Odometer: 68474 km

Engine Capacity: 1395 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,255.75	2,154.62	1,101.13	33.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,680.00	2,400.00	3,280.00	57.75
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	8,935.75	4,554.62	4,381.13	49.03
	+ GST 7.00/7.00% (S\$)	625.50	318.82	306.68	49.03
	Nett Amount (S\$)	9,561.25	4,873.44	4,687.81	49.03
		CCEO 00/d) (CC)	200.00		

+ Loss of Use (4.0 x S\$50.00/day) (S\$) 200.00 + Doc/Search Fee (S\$) 7.45

Nett Liability (S\$) 5,080.89

INSPECTION

Date of Assignment: 18/11/2021

Volkswagen Group Singapore Pte Ltd

Date Inspected: 19/11/2021 Inspected At: 247 ALEXANDRA ROAD

Singapore 159934

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Jan 2022)

Parts: N/A VOLKSWAGEN SPORTSVAN 1.4 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL4534U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No	. Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,359.58 FS	*1,359.58 FS
2	1		*FOAM INSERT	Not Necessary	44.24 FS	*-FS
3	1		*SUPPORT PART RHS BUMPER INNER BRACKET	Cracked	35.92 FS	*35.92 FS
4	1		*GUIDE PIECE RHS BUMPER SIDE BRACKET	Not Necessary	22.85 FS	*-FS
5	1		*GUIDE PIECE LHS BUMPER SIDE BRACKET	Not Necessary	22.85 FS	*-FS
6	1		*GUIDE BUMPER CTR BRACKET	Not Necessary	85.30 FS	*-FS
7	1		*RADIATOR GRILLE BLACK /SAT	Not Necessary	459.44 FS	*-FS
8	1		*COOLING AIR GRILLE SATIN B BUMPER CTR LOWER GRILLE	Not Necessary	136.10 FS	*-FS
9	1		*TWIN HALOGEN HEADLAMPS	Scratched	759.12 FS	*759.12 FS
10	1		*FLAT CONLACT HOUSING H/LAMP WIRE HOUSING	Not Necessary	21.17 FS	*-FS
11	1		*HALOGEN FOG LAMP	Not Necessary	279.62 FS	*-FS
12	1		*COVER PART FOR BUMPER SAT RHS FOG LAMP GRILLE	Not Necessary	29.56 FS	*-FS
F=Fra	nchise	part. S=Sp	cNett.	T. (. D ((OA)	0.055.75	0.454.00
				Total Parts (S\$)	3,255.75	2,154.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINT	New	2,400.00	800.00
		Gross Labour Cost (S\$)	5,680.00	2,400.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >