

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011783/BTY3N2**Date:** 25/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00005482100
Claimant Vehicle No :	SLB6453J	Insured Vehicle No :	SJT4793U
Date of Loss:	14/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206576/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6453J		
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT ABS D/AIRBAG 2WD (A)	Engine No:	L15B31020961
Reg. Date:	15/04/2016 (Man. Year: 2016)	Chassis No:	JHMGK5850GX202392
Colour:	Purple	Odometer:	120900 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,309.56	3,185.68	5,123.88	61.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,580.00	2,320.00	59.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,209.56	4,765.68	7,443.88	60.97
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	12,209.56	3,800.00	8,409.56	68.88
+ GST 7.00/7.00% (\$\$)	854.67	266.00	588.67	68.88
Nett Amount (\$\$)	13,064.23	4,066.00	8,998.23	68.88

INSPECTION

Date of Assignment:	20/03/2022	
Date Inspected:	19/11/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: DENISE TAY KWEE CHENG**Manager:** Lim Teow Guan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: 144 HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB6453J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	592.20 FL	*592.20 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Necessary	48.90 FL	*26.40 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Necessary	48.90 FL	*26.40 FL
4	1		*LH REAR FENDER	Dented	629.90 FL	*629.90 FL
5	1		*LH REAR FENDER GLASS WITH RUBBER SEAL	Necessary	182.90 FL	*182.90 FL
6	1		*LH REAR FENDER INNER TRIM BOARD	Not Damaged	185.60 FL	*- FL
7	1		*LH REAR FENDER SPLASH SHIELD	Not Damaged	90.30 FL	*- FL
8	1		*LH REAR FENDER INNER LOWER DUCT	Not Damaged	24.70 FL	*- FL
9	1		*LH TAILLAMP ASSY	Not Damaged	223.90 FL	*- FL
10	1		*LH SIDE ROCKER PANEL GARNISH	Dented	294.50 FL	*294.50 FL
11	1		*LH REAR DOOR	Dented	822.30 FL	*822.30 FL
12	1		*LH REAR DOOR FRAME BLACK TAPE	Necessary	38.20 FL	*20.00 FL
13	1		*LH REAR SPORT RIM	Cut	693.50 FL	*350.00 FL
14	1		*LH REAR SHOCK ABSORBER	Not Damaged	259.90 FL	*- FL
15	1		*LH REAR WHEEL BEARING	Jammed	198.20 FL	*198.20 FL
16	1		*REAR AXLE BAEM	Not Damaged	1,205.80 FL	*- FL
17	1		*LH FRONT SPORT RIM	Cut	693.50 FL	*350.00 FL
18	1		*LH FRONT SHOCK ABSORBER	Not Damaged	310.70 FL	*- FL
19	1		*LH FRONT LOWER ARM	Not Damaged	175.80 FL	*- FL
20	1		*LH FRONT KNUCKLE ARM	Not Damaged	230.90 FL	*- FL
21	1		*LH FRONT WHEEL BEARING	Jammed	126.80 FL	*126.80 FL
22	1		*LH FRONT DRIVE SHAFT	Not Damaged	831.40 FL	*- FL
23	1		*LH FRONT TIE ROD END	Not Damaged	72.30 FL	*- FL
24	1		*STEERING RACK AND PINION	Not Damaged	1,262.10 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
26	1		*LH REAR FENDER GLASS SEALANT	Necessary	60.00 FS	*30.00 FS
27	1		*LH REAR FENDER GLASS INNER SEAL	Necessary	40.00 FS	*20.00 FS
28	1		*LH REAR FENDER JOINT SEALANT	Necessary	70.00 FS	*30.00 FS
29	1		*BRAKE FLUID	Not Necessary	55.00 FS	*- FS
30	1		*LH SIDE ROCKER PANEL GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
31	1		*LH FRONT TYRE	Cut	280.00 FS	*150.00 FS
32	1		*LH REAR TYRE	Not Damaged	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,158.20	3,909.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,848.64	723.92
Total Parts (\$\$)	8,309.56	3,185.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	70.00	0.00
5	REMOVE AND REPLACE REAR INNER TRIMS,GARNISH,SEATS,ROOF LINING AND CARPET TO ASSIST REPAIR	New	320.00	0.00
6	REMOVE AND REINSTALL REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	80.00	60.00
7	REMOVE AND REINSTALL LH REAR FENDER GLASS TO ASSIST REPAIR	New	100.00	40.00
8	REMOVE AND REINSTALL FUEL TANK,PIPE,HOSES AND SENSORS TO ASSIST REPAIR	New	180.00	0.00
9	REMOVE AND REINSTALL LH REAR DOOR INNER COMPONENTS TO ASSIST REPAIR	New	120.00	80.00
10	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	450.00	0.00
11	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	400.00	0.00
12	CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
Gross Labour Cost (\$\$)			3,900.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >