

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21011790/EVF3N2**Date:** 09/12/2021**REFERENCE**

Insured/Claimant: THYE POH CHIN WILLIAM @ JOHN BIN ABDULLAH Policy No: 7210031872
Date of Loss: 18/11/2021 Nature of Claim: OD Claim No: 6005924965SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY9439Z**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGLH712926
Reg. Date: 31/03/2021 (Man. Year: 2020) Chassis No: KNAF5416MM5103060
Colour: Grey Odometer: 9393 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Kumho 4 mm Rear Left Side: Kumho 4 mm
Front Right Side: Kumho 4 mm Rear Right Side: Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,314.78	5,416.78	898.00	14.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	2,720.00	1,200.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,234.78	8,136.78	2,098.00	20.50
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	9,934.78	7,836.78	2,098.00	21.12
+ GST 7.00/7.00% (S\$)	695.43	548.57	146.86	21.12
Nett Amount (S\$)	10,630.21	8,385.35	2,244.86	21.12

INSPECTION

Date of Assignment: 18/11/2021
Date Inspected: 19/11/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD LH	Broken	2,210.00 FL	*2,210.00 FL
2	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
3	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
4	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
5	1		*GRILLE-FRONT BUMPER	Cut	485.00 FL	*485.00 FL
6	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
7	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
8	1		*MOULDING-FRONT BUMPER,LH	Broken	216.00 FL	*216.00 FL
9	1		*LAMP ASSY-SIDE REPEATER,LH	Broken	143.00 FL	*143.00 FL
10	1		*AIR DUCT-FR BUMPER,LH	Broken	14.00 FL	*14.00 FL
11	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
12	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
13	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
14	1		*WIRING ASSY-BUMPER EXTENSION	Not Necessary	207.00 FL	*- FL
15	2		*ULTRASONIC SENSOR ASSY-P.A.S	Not Necessary	326.00 FL	*- FL
16	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
17	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
18	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
19	1		*BODY PNL SEALANT	Necessary	60.00 FS	*40.00 FS
20	1		*FR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
21	1		*COVER-FR BUMPER FOG LAMP, LH (Supplementary)	Cut	15.00 FL	*15.00 FL
22	1		*ORNAMENT-KIA NO 115 (Supplementary)	Necessary	32.00 FL	*32.00 FL
23	10		*CLIP (Supplementary)	Necessary	10.00 FL	*10.00 FL
24	1		*BUZZER ASSY-PIEZO (Supplementary)	Broken	58.00 FL	*58.00 FL
25	1		*ANTIFREEZER (Supplementary)	Necessary	108.98 FL	*108.98 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,860.98	6,755.98
- List Item Discount on L Items 20.00/20.00% (\$)	1,546.20	1,339.20
Total Parts (\$)	6,314.78	5,416.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER,BONNET & FR SUPPORT PNL.REPAIR LHF FENDER	New	2,000.00	800.00
2	RESPRAY FR BUMPER,BONNET & LHF FENDER	New	1,050.00	1,050.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AC GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
8	MOUNTED ONTO FLOOR BENCH TO STRAIGHTEN FRONT CHASSIS (Supplementary)	New	500.00	500.00
Gross Labour Cost (\$\$)			3,920.00	2,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >