



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

KIA
Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV14007/THYE POH CHIN WILLIAM @JOHAN BI Reg No/Reg Date SMY9439Z / 31/03/202 Date In/Mileage / 9393 Chassis No KNAF5416MM5103060 Engine No G4FGLH712926 Make/Model KIA/CERATO 1.6 A GT LINE H370 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/11/2021/ 16:51	BLE	261 / Edwin Caina	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , BONNET & FR SUPPORT PNL					2 X 400			800
REPAIR LHF FENDER								1050.00
E PNT98000								100.00
RESPRAY FR BUMPER , BONNET & LHF FENDER					3 X 350			100.00
E PNT88000								80.00
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								30.00
TOP UP AC GAS								30.00
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								120.00
A 10028901								50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY								40.00
SUPPLY FR NUMBER PLATE WITH CASING								40.00
M SUNDRY								60.00
APPLY ANTI CORROSION ON AFFECTED AREAS								60.00
M SUNDRY								20.00
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								1768.00
Sundries					1.00	2210.00	20.00	1768.00
M LAMP ASSY-HEAD,LH					1.00	1502.00	20.00	1201.60
M PANEL ASSY-HOOD					13.00	1.00	20.00	10.40
M CLIP-HOOD INSULATING PAD MTG					1.00	633.00	20.00	506.40
M COVER-FR BUMPER					1.00	485.00	20.00	388.00
M GRILLE-FRONT BUMPER					1.00	328.00	20.00	262.40
M GRILLE ASSY-RADIATOR					1.00	38.00	20.00	30.40
M GARNISH-RADIATOR GRILLE					1.00	216.00	20.00	172.80
M MOULDING-FRONT BUMPER,LH					1.00	143.00	20.00	114.40
M LAMP ASSY-SIDE REPEATER,LH					1.00	14.00	20.00	11.20
M AIR DUCT-FR BUMPER,LH					1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	114.00	20.00	91.20
M STIFFNER-FR BPR LWR								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>LCV14007/THYE POH CHIN WILLIAM @JOHAN BI</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMY9439Z / 31/03/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 9393</td></tr> <tr> <td>Chassis No</td><td>KNAF5416MM5103060</td></tr> <tr> <td>Engine No</td><td>G4FGLH712926</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A GT LINE H370</td></tr> <tr> <td>Colour/Trim</td><td>KLG STEEL GREY / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI	Reg No/Reg Date	SMY9439Z / 31/03/202	Date In/Mileage	/ 9393	Chassis No	KNAF5416MM5103060	Engine No	G4FGLH712926	Make/Model	KIA/CERATO 1.6 A GT LINE H370	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK
Cust No/Name	LCV14007/THYE POH CHIN WILLIAM @JOHAN BI														
Reg No/Reg Date	SMY9439Z / 31/03/202														
Date In/Mileage	/ 9393														
Chassis No	KNAF5416MM5103060														
Engine No	G4FGLH712926														
Make/Model	KIA/CERATO 1.6 A GT LINE H370														
Colour/Trim	KLG STEEL GREY / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	18/11/2021/ 16:51	BLE	261 / Edwin Caina	42700			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	WIRING ASSY-BUMPER EXTENSION				1.00	207.00	20.00	165.60
M	ULTRASONIC SENSOR ASSY-P.A.S				2.00	163.00	20.00	260.80
M	BEAM COMPLETE-FR BUMPER				1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE				1.00	675.00	20.00	540.00

Estimate

Steve (LKK)

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

5 days

OB M AL

EXCEPT - ?

PIP

My Bill

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

7% GST on	Nett	9,555.60
		668.89
	Total Payable	10,224.49

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.