

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011791/T1TY3N2**Date:** 13/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00181752100

Claimant Vehicle No : SKS1844U **Insured Vehicle No :** SFJ933J

Date of Loss: 16/11/2021 Nature of Claim: TP Claim No: SNM21D206600/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS1844U**

Make & Model: NISSAN ALMERA, 1.5 (A) Engine No: HR15972109C

Reg. Date: 30/03/2015 (Man. Year: 2014) Chassis No: MNTBBAN17Z0500063

Colour: Black Odometer: 81062 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,649.44	1,241.28	408.16	24.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,448.00	2,428.00	1,020.00	29.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,097.44	3,669.28	1,428.16	28.02
+ GST 7.00/7.00% (S\$)	356.82	256.85	99.97	28.02
Nett Amount (S\$)	5,454.26	3,926.13	1,528.13	28.02

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 19/11/2021 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2021)
Parts:	143	NISSAN ALMERA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS1844U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM T/LID ALMERA	Necessary	59.90 FN	*59.90 FN
2	1		*EMBLEM REAR NISSAN	Necessary	59.90 FN	*59.90 FN
3	1		*REAR END PANEL	Bent	434.90 FN	*434.90 FN
4	2		*STAY RR BUMPER	Not Necessary	193.80 FN	*- FN
5	1		*ENERGY ABSORBER RR BUMPER	Not Necessary	141.40 FN	*- FN
6	1		*LH SIDE BRACKET RR BUMPER	Necessary	42.50 FN	*42.50 FN
7	1		*RH SIDE BRACKET RR BUMPER	Necessary	42.50 FN	*42.50 FN
8	10		*CLIP RR BUMPER	Necessary	13.00 FN	*13.00 FN
9	1		*REAR BUMPER	Deformed	561.40 FN	*561.40 FN
10	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
11	1		*SENSOR-REVERSE	Not Working	250.00 FS	*250.00 FS
12	1		*REAR LICENCE PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	1,959.30	1,484.10
- Nett Item Discount on N Items 20.00/20.00% (\$)	309.86	242.82
Total Parts (\$)	1,649.44	1,241.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR TRUNKFLOOR & TRUNKLID RENEW RR END PANEL AND REAR BUMPER	New	1,400.00	1,120.00
2	CHARGES TO SPRAY PAINTING TRUNKFLOOR,RR END PANEL TRUNKLID AND REAR BUMPER	New	1,250.00	750.00
3	RENEW REVERSE SENSOR	New	110.00	110.00
4	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	New	48.00	48.00
5	APPLY SEALANT TO REAR END PANEL	New	100.00	100.00
6	COMPLETE VEHICLE POLISHING	New	180.00	0.00
7	COMPUTER CHECK DIAGNOSIS	New	120.00	120.00
8	REMOVE AND INSTALL BOTH INNER TRIM RR FENDER	New	240.00	180.00
Gross Labour Cost (\$)			3,448.00	2,428.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >