

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS1844U

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & TRUNKLID RENEW RR END PANEL AND REAR BUMPER	280 1400.00	1120 ✓
2 ZZ/002	CHARGES TO SPRAY PAINTING TRUNKFLOOR,RR END PANEL TRUNKLID AND REAR BUMPER	250 1250.00	750 ✓
3 ZZ/003	RENEW REVERSE SENSOR	110.00	✓ /
4 ZZ/004	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	48.00	✓ /
5 ZZ/005	APPLY SEALANT TO REAR END PANEL	100.00	✓ /
6 ZZ/006	COMPLETE VEHICLE POLISHING	180.00	X n n
7 ZZ/007	COMPUTER CHECK DIAGNOSIS	120.00	✓ /
8 ZZ/008	REMOVE AND INTALL BOTH INNER TRIM RR FENDER	240.00	180 ✓
TOTAL LABOUR CHARGES		3448.00	2428

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS1844U

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			100.00 20
2 SENSOR-REVERSE	SENSOR			250.00 nu-
3 EMBLEM T/LID ALMERA	84895-3BB0A	59.90	na	
4 EMBLEM REAR NISSAN	84890-3AA0A	59.90	na	
5 REAR END PANEL	G9110-3BGMA	434.90	bb	
6 STAY RR BUMPER @ SGD\$96.90 EACH	H5212-1HMMMA	193.80	Run	
7 ENERGY ABSORBER RR BUMPER	85090-7W80A	141.40	Run	
8 LH SIDE BRACKET RR BUMPER	85220-3BG0A	42.50	all	
9 RH SIDE BRACKET RR BUMPER	85221-3BG0A	42.50	all	
10 CLIP RR BUMPER @ SGD \$1.30 EACH	01553-10501	13.00	all	
11 REAR BUMPER	85022-7W83H	561.40	all	
12 REAR LICENCE PLATE	RLP			60.00 X nu.
SUB TOTAL		1549.30	0.00	410.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		309.86	0.00	0.00
GRAND TOTAL		1239.44	0.00	410.00
OVERALL TOTAL		1649.44		

1214.10 SN 270
971.28

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

2428
971.28
270
\$ 3669.28 #
7 days