


ASS. REC. BY: Tang JH REF: 01C712101791/71143

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$38K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS/8444 Yr Regn: 2015, March
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Nissan A/Merq c.c 1498
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 81062 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MNT BBAN 17 E050063
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modl: NI / S/Rim / STD A/Rim or _____
Tyre Size: F: 185/65R15
R: 185/65R15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 19/4/21
Survey held at Autobahn
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	FINALISE AT COR \$3669.28 . 7 days
	RED: 1428.16;28%

Date/Time, File Pass to? ☐ : Prell. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____
Rep. Format : _____
Lump Sum / L.S. / C.F. _____

Days Of Repair: 7
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____
TOTAL _____

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0404/21

DATE : 16-NOV-2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63896111

FAX : 62247175

OWNER'S NAME : A ZONE CORPORATION PTE LTD

ADDRESS : 14 LOYANG DRIVE

S(608941)

TELEPHONE NO : 65454800/97220103

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 2100407534-06

VEHICLE NO : SKS1844U

MODEL CODE : BDUARGAN17EWA-----E4

MODEL/YEAR : NISSAN ALMERA 1.5L AT COMFORT EURO4

ENGINE NO : HRI5972109C

CHASSIS NO : MNTBBAN1720500063

MILEAGE : 80959 KM

DATE IN : 16/11/2021

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 16/11/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 9645 0084 elmy@tanchong.com

Taufik 97495749/62563561

WP

19/11/21 215pm

P/P Resurvey before permit

taufik@khantaw

7 days

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKS1844U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR TRUNKFLOOR & TRUNKLID RENEW RR END PANEL AND REAR BUMPER	280 1400.00	1120.
2	ZZ/002	CHARGES TO SPRAY PAINTING TRUNKFLOOR,RR END PANEL TRUNKLID AND REAR BUMPER	250 1250.00	750.
3	ZZ/003	RENEW REVERSE SENSOR	110.00	✓
4	ZZ/004	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	48.00	✓
5	ZZ/005	APPLY SEALANT TO REAR END PANEL	100.00	✓
6	ZZ/006	COMPLETE VEHICLE POLISHING	180.00	X
7	ZZ/007	COMPUTER CHECK DIAGNOSIS	120.00	✓
8	ZZ/008	REMOVE AND INTALL BOTH INNER TRIM RR FENDER	240.00	180.
TOTAL LABOUR CHARGES			3448.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKS1844U

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES	NPN		100.00 20
2	SENSOR-REVERSE	SENSOR		250.00 nu-
3	EMBLEM T/LID ALMERA	84895-3B80A	59.90	na
4	EMBLEM REAR NISSAN	84890-3A40A	59.90	na
5	REAR END PANEL	69110-3B6MA	434.90	bb
6	STAY RR BUMPER @ SGD\$96.90 EACH	H5212-1HMMA	193.80	?
7	ENERGY ABSORBER RR BUMPER	85090-7W80A	141.40	?
8	LH SIDE BRACKET RR BUMPER	85220-3B60A	42.50	na
9	RH SIDE BRACKET RR BUMPER	85221-3B60A	42.50	na
10	CLIP RR BUMPER @ SGD \$1.30 EACH	01553-10501	13.00	na
11	REAR BUMPER	85022-7W83H	561.40	na
12	REAR LICENCE PLATE	RLP		60.00 X
SUB TOTAL			1549.30	0.00 410.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			309.86	0.00 0.00
GRAND TOTAL			1239.44	0.00 410.00
OVERALL TOTAL			1649.44	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKS1844U

TOTAL LABOUR CHARGES	3448.00
TOTAL SPARE PARTS CHARGES	1649.44

GRAND TOTAL	5097.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.