



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203632

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/06/2022
Reference CC3/CTI21011794/Gea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 5561J
Insured Veh. SJU 9400R
Claim No. SNM21D206537/C02
Policy No. DMPCSNW00197592000
Accident Date 13/11/2021
Inspection Date 16/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21011794/Gea3q2 Date: 13/06/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 9400R	Veh. Inspected	SHB 5561J	
Policy No.	DMPCSNW00197592000	Coverage (\$)	0.00	
Claim No.	SNM21D206537/C02	Excess (\$)	0.00	
Assign From		Assign Date	16/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU303088927	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	13/11/2021	Inspection Date	16/11/2021	
Survey held at	STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5561J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GAE BACK DOOR OUTSIDE GARNISH SUB (DISC 25%)	CUT	913.60	685.20
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	47.90	35.93
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	54.60	40.95
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	54.60	40.95
2	PAD ,RR BUMPER ,RH & LH ,1 @\$4.00 (DISC 25%)	NECESSARY	8.00	6.00
3	PAD ,RR BUMPER CTR @\$11.00 (DISC 25%)	NECESSARY	33.00	24.75
2	SEAL ,RR BUMPER ARM ,RH & LH @\$11.30 (DISC 25%)	NECESSARY	22.60	16.95
10	CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	NECESSARY	45.00	33.75
1	GUARD ,RR BUMPER LOWER (DISC 25%)	NECESSARY	374.50	280.88
1	COVER GUARD RR BUMPER LOWER (DISC 25%)	DEFORMED	22.00	16.50
1	COVER ,RR BUMPER ASSY (DISC 25%)	DEFORMED	485.60	364.20
2	PAD ,RR BUMPER ,RH & LH 3 @\$11.00 (DISC 25%)	NECESSARY	22.00	16.50
2	PAD ,RR BUMPER ,RH & LH 2 @\$4.00 (DISC 25%)	NECESSARY	8.00	6.00
1	LENS & BODY REAR COMBINATION LAMP ,RH (DISC 10%)	CRACKED	339.60	305.64
1	LAMP ASSY ,REAR RH (DISC 10%)	CRACKED	293.60	264.24
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	ANTENNA ELECTRICAL KEY	NOT NECESSARY	72.00	-
1	PANEL SUB-ASSY ,FENDER REAR RH	NOT NECESSARY	871.50	-
2	DUCT ASSY ,QUARTER VENT ,RH& LH	NOT NECESSARY	67.00	-
1	LINER REAR FENDER, RH	NOT NECESSARY	139.80	-
1	END PANEL SUB-ASSY BODY LOWER BACK	NOT NECESSARY	651.00	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	REAR BUMPER REFLECTOR ASSY ,REFLEX LH	NOT NECESSARY	39.00	-
1	COVER ,REAR FLOOR UNDER ,RH	NOT NECESSARY	175.10	-
1	COVER ,REAR FLOOR UNDER ,LH	NOT NECESSARY	241.90	-

Report Ref No. CC3/CTI21011794/Gea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER ,REAR FLOOR UNDER CENTER	NOT NECESSARY	229.90	-
1	COVER REAR COMBINATION LAMP RH	NOT NECESSARY	69.90	-
1	LENS & BODY ,REAR COMBINATION LAMP ,NO.2	NOT NECESSARY	261.00	-
1	RETAINER ,RR BUMPER ,RH	NOT NECESSARY	132.60	-
1	RETAINER ,RR BUMPER ,LH	NOT NECESSARY	132.60	-
1	SEAL ,RR BUMPER ,RH	NOT NECESSARY	118.30	-
1	REAR BUMPER REFLECTOR ASSY ,REFLEX ,RH	NOT NECESSARY	39.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	332.70	-
1	SPOILER SUB-ASSY REAR	NOT NECESSARY	1,575.40	-
			8,239.70	2,467.84
	LABOUR			
	PANEL BEATING & BODY WORK.		676.00	300.00
	SPRAY PAINT.		1,476.00	300.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM .		120.00	40.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,512.00	670.00
GRAND TOTAL			10,751.70	3,137.84
RECOMMENDED COST OF REPAIRS				3,137.84

Report Ref No. CC3/CTI21011794/Gea3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5561J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHB 5561J

RE-INSPECTION

