

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011803/UTY3N2**Date:** 01/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00010242100

Claimant Vehicle No : SMD7994K **Insured Vehicle No :** XE6346C

Date of Loss: 18/11/2021 Nature of Claim: TP Claim No: SNM21D206665/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD7994K**

Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A) Engine No: D4FDJD025914

Reg. Date: 05/09/2018 (Man. Year: 2018) Chassis No: KNAHU815VJ7211485

Colour: Brown Odometer: 259661 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: DURATURN 6 mm Rear Left Side: DURATURN 6 mm

Front Right Side: DURATURN 6 mm Rear Right Side: DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,245.88	2,498.70	2,747.18	52.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,880.00	900.00	32.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,025.88	4,378.70	3,647.18	45.44
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	8,025.88	3,500.00	4,525.88	56.39
+ GST 7.00/7.00% (S\$)	561.81	245.00	316.81	56.39
Nett Amount (S\$)	8,587.69	3,745.00	4,842.69	56.39

INSPECTION

Date of Assignment: 22/11/2021

Date Inspected: 19/11/2021 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2021)**Parts:** M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMD7994K)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	676.00 FL	*605.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
3	1		*REAR BUMPER PAD	Not Necessary	189.00 FL	*- FL
4	1		*REAR BUMPER LOWER DIFFUSION	Not Necessary	285.00 FL	*- FL
5	1		*O/S REAR BUMPER REFLECTOR	Not Necessary	139.20 FL	*- FL
6	1		*O/S REAR BUMPER PARKING SENSOR	Not Necessary	168.00 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER O/S	Cracked	46.00 FL	*46.00 FL
8	1		*O/S REAR FENDER	Badly Dented	1,223.00 FL	*1,223.00 FL
9	1		*O/S REAR FENDER INNER COWLING	Torn	224.00 FL	*181.00 FL
10	8		*O/S REAR FENDER INNER COWLING CLIPS	Necessary	40.00 FL	*40.00 FL
11	1		*O/S REAR FENDER AIR VENT	Not Necessary	28.00 FL	*- FL
12	1		*O/S REAR FENDER WHEEL ARC GARNISH	Not Necessary	158.00 FL	*- FL
13	1		*O/S TAILLAMP	Not Necessary	878.00 FL	*- FL
14	1		*O/S REAR DOOR	Repair	842.00 FL	*- FL
15	1		*O/S REAR DOOR LOCK	Not Necessary	229.00 FL	*- FL
16	1		*O/S REAR WHEEL SPORT RIM	Cut	605.00 FL	*605.00 FL
17	1		*O/S REAR FENDER QUARTER GLASS SEALANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,823.20	2,773.00
- List Item Discount on L Items 10.00/10.00% (S\$)	577.32	274.30
Total Parts (S\$)	5,245.88	2,498.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT RIGHT REAR FENDER QUARTER GLASS	New	120.00	80.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	50.00
3	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	100.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
6	TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SEAT AND SEAT FRAME AND RECLINING MECHANISM	New	100.00	80.00
7	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,200.00	800.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	950.00	800.00
			Gross Labour Cost (\$)	2,780.00
				1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >