

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SMD7994K  
at Workshop m/s: Yarku  
of: XEB346C  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £ 70k.  
IDAC Accident Rport: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 5 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS C O/S & D  
Date: \_\_\_\_\_ Person Contacted: Dep Rep

Veh No: SMD7994K Yr Regn: 05/09/18  
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CAI  
Make: KIA carens c.c 1685  
Colour: Brown A/C: Insured / Std / NI / NA  
Sp.Reading: 259661 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: KNAHU85VJ721145  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 205/55-216  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Dura Turn  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 18/11/12 D.O.I. 19/11/12  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
015 Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

27/11/12 LYA #36182 confirmed with millan.  
red:4525.88; 56%

Date/Time, File Pass to?  Preli. Report  
 Final Report

Days Of Repair:  
Resurvey No. of Trip:

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Report Format :  
Lump Sum / I.B.I: (\$ )

CTP Insured's Veh No : XE6346C  
 Date of Accident : 18 November 2021

*not Holland  
 like  
 1/5 # 3500  
 Skys.  
 the pho Attorney.  
 19/11/21*



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

1 Defu Lane 6 Singapore 539365  
 Tel : 68585151 (24 Hours) Fax : 68580877  
 GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal Responsibility is on "Without Prejudice" basis
- Date: 19 November 2021
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Acknowledged by Repairer
- Signed by Repairer

Estimate To Repair SMD7994K - KIA CARENS 1.7 DCT DIESEL 5DR FWD  
 Chassis No : KNAHU815VJ7211485

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	1 pc	rear bumper <i>DIS 605</i>	\$ 676.00
02	10 pcs	rear bumper clips @ \$4.30 <i>ALL</i>	\$ 43.00
03	1 pc	rear bumper pad <i>11</i>	\$ 189.00
04	1 pc	rear bumper lower diffusion <i>11</i>	\$ 285.00
05	1 pc	o/s rear bumper reflector <i>11</i>	\$ 139.20
06	1 pc	o/s rear bumper parking sensor <i>11</i>	\$ 168.00
07	1 pc	rear bumper side retainer o/s <i>ONE</i>	\$ 46.00
08	1 pc	o/s rear fender <i>300500</i>	\$ 1,223.00
09	1 pc	o/s rear fender inner cowling <i>TURN</i>	\$ 224.00
10	8 pcs	o/s rear fender inner cowling clips @ \$5.00 <i>ALL 181</i>	\$ 40.00
11	1 pc	o/s rear fender air vent <i>11</i>	\$ 28.00
12	1 pc	o/s rear fender wheel arc garnish <i>11</i>	\$ 158.00
13	1 pc	o/s taillamp <i>11</i>	\$ 878.00
14	1 pc	o/s rear door <i>11</i>	\$ 842.00
15	1 pc	o/s rear door lock <i>11</i>	\$ 229.00
16	1 pc	o/s rear wheel sport rim <i>CU7</i>	\$ 605.00
Less 10 %			\$ 5,773.20
			\$ 577.32
			\$ 5,195.88
<b>SPECIAL NETT ITEMS</b>			
17	1 pc	o/s rear fender quarter glass sealant <i>ALL</i>	\$ 50.00
			\$ 50.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To remove and refit right rear fender quarter glass.	\$ 120.00
02		To rust-proofing of the affected areas.	\$ 150.00
03		To transfer of door fittings and perform water seepage test.	\$ 100.00
04		To check electrical lighting concerned.	\$ 80.00
05		To reinstall of rear bumper parking sensor.	\$ 80.00
06		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism.	\$ 100.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
08		Putty and spray painting of the affected portion.	\$ 950.00
			\$ 2,780.00
Total			\$ 8,025.88

*P-2743  
 102  
 2468.7  
 (3368.7)*

*Handwritten checkmarks and numbers in the right margin of the table, including '30', '80', '50', '20', '50', '80', '800', '800'.*