

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011811/GTF3E2

Date: 12/01/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263838
Claimant Vehicle No :	SMR4073P	Insured Vehicle No :	SGB7087K
Date of Loss:	18/11/2021	Nature of Claim:	TP
		Claim No:	6434067133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4073P	Engine No:	274AE048017A
Make & Model:	INFINITI Q50, 2.0 T (R18) EU6 NAV (A)	Chassis No:	JN1BCAV37Z0510039
Reg. Date:	19/10/2016 (Man. Year: 2016)	Odometer:	120326 km
Colour:	Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/11/2021	Revol Carz Garage Pte Ltd (HQ)
Date Inspected:	19/11/2021 Inspected At:	Block 10, Ang Mo Kio Ind Park 2A, #02-18, AMK Auto Point
Estimated Period of Repair:	4.0 days	Singapore 568047

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$75,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER LH	Distorted	0.00 F	*- F
4	2		*REVERSE SENSOR	Shorted	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
10	1		*BOOTLID LOCK	Bent	0.00 F	*- F
11	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >