



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 2251M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	1,192.00	1,192.00
1	TAILGATE "H" EMBLEM	NOT NECESSARY	38.00	-
1	TAILGATE "SHUTTLE" EMBLEM	NECESSARY	58.00	58.00
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	75.00	75.00
	LESS 20% DISCOUNT		-272.60	-265.00
			1,090.40	1,060.00
<u>SPECIAL NETT ITEMS</u>				
1	"PRIME TAXI" STICKER (SN)	NECESSARY	55.00	55.00
1	"DIAL A CAB 6778 0808" STICKER (SN)	NOT NECESSARY	45.00	-
1	TUBE GLASS SEALANT (SN)	NECESSARY	40.00	40.00
			140.00	95.00
<u>LABOUR</u>				
	TO TUFF KOTE REAR AFFECTED PORTION.		50.00	30.00
	TO TRANSFER TAIL GATE TRIM BOARD,HANDLE,MECHANISM PARTS.		80.00	50.00
	TO REMOVE & REFIT REAR GLASS.		120.00	120.00
	TO REPAIR REAR BUMPER,REMOVE & REPLACE TAILGATE.ALIGN & ADJUST TAILGATE.		500.00	200.00
	TO PUTTY,RESPRAY PAINTING TAIL GATE'S INLET & OUTER AND REAR BUMPER.TO POLISH.		500.00	200.00
			1,250.00	600.00
GRAND TOTAL			2,480.40	1,755.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/SMR21011818/Euf3n2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.