

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011821/URS3Q2**Date:** 19/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900233152
Claimant Vehicle No :	SMA4187J	Insured Vehicle No :	SMP9980Z
Date of Loss:	19/11/2021	Nature of Claim:	TP
		Claim No:	9262814862SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4187J	Engine No:	A25A0116767
Make & Model:	TOYOTA CAMRY, 2.5 G HYBRID CVT (A)	Chassis No:	AXVH701023120
Reg. Date:	06/06/2018 (Man. Year: 2018)	Odometer:	62757 km
Colour:	Brown		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,099.20	3,765.20	1,334.00	26.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,055.00	1,910.00	1,145.00	37.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,154.20	5,675.20	2,479.00	30.40
+ GST 7.00/7.00% (S\$)	570.79	397.26	173.53	30.40
Nett Amount (S\$)	8,724.99	6,072.46	2,652.53	30.40
+ Car Rental (8.0 x S\$87.50/day) (S\$)		700.00		
Nett Liability (S\$)		6,772.46		

INSPECTION

Date of Assignment:	19/11/2021		
Date Inspected:	19/11/2021	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Dented	928.20 FL	*928.20 FL
2	1	*REAR BOOTLID BADGE	Not Necessary	59.20 FL	*- FL
3	1	*REAR BOOTLID HYBRID SYNERGY DRIVE EMBLEM	Necessary	77.40 FL	*77.40 FL
4	1	*REAR BOOTLID WEATHERSTRIP (RUBBER)	Twisted	195.50 FL	*195.50 FL
5	1	*REAR BOOTLID LOCK	Serviceable	478.50 FL	*- FL
6	1	*REAR BOOTLID RH REFLECTOR	Not Necessary	567.40 FL	*- FL
7	1	*REAR RH TAIL LAMP	Cracked	669.50 FL	*669.50 FL
8	1	*REAR RH TAIL LAMP LOWER RETAINER	Cracked	92.80 FL	*92.80 FL
9	1	*REAR TAIL LAMP SIDE COVER	N/S Not Necessary / O/S Cut	65.40 FL	*32.70 FL
10	1	*REAR BUMPER	Dented	1,296.60 FL	*1,296.60 FL
11	1	*SET REAR BUMPER CLIPS	Necessary	47.00 FL	*47.00 FL
12	1	*REAR BUMPER RH RED REFLECTOR	Not Necessary	54.40 FL	*- FL
13	1	*BUMPER REINFORCEMENT	Dented	361.60 FL	*361.60 FL
14	1	*REAR BUMPER LOWER COVER	Deformed	466.10 FL	*450.10 FL
15	1	*REAR BUMPER RH SIDE RETAINER	Not Necessary	133.20 FL	*- FL
16	1	*END PANEL	Badly Dented	602.20 FL	*602.20 FL
17	1	*END PANEL TOP GARNISH	Not Necessary	309.80 FL	*- FL
18	4	*END PANEL TOP GARNISH CLIPS	Not Necessary	20.80 FL	*- FL
19	1	*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
20	1	*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL
21	1	*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,705.60	4,953.60
- List Item Discount on L Items 25.00/25.00% (\$)	1,606.40	1,188.40
Total Parts (\$)	5,099.20	3,765.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR REVERSE SENSOR	New	80.00	50.00
2	LABOUR CHARGE	New	1,250.00	800.00
3	SPRAY PAINTING	New	1,450.00	900.00
4	TUFF COAT	New	120.00	60.00
5	WIRING	New	35.00	20.00
6	LABOUR TO REMOVE & REFIX CARPETS & GARNISHES	New	120.00	80.00
Gross Labour Cost (\$\$)			3,055.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >