

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011822/UTY3N2
Date: 01/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00195032101
Claimant Vehicle No :	SJB2633G	Insured Vehicle No :	SJK1835A
Date of Loss:	18/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206653/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB2633G	Engine No:	4G18JM6675
Make & Model:	mitsubishi LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U004655
Reg. Date:	07/01/2008 (Man. Year: 2007)	Odometer:	232819 km
Colour:	Grey		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,700.20	4,994.50	4,705.70	48.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	2,270.00	1,130.00	33.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,100.20	7,264.50	5,835.70	44.55
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	13,100.20	5,800.00	7,300.20	55.73
+ GST 7.00/7.00% (S\$)	917.01	406.00	511.01	55.73
Nett Amount (S\$)	14,017.21	6,206.00	7,811.21	55.73

INSPECTION

Date of Assignment:	22/11/2021	
Date Inspected:	19/11/2021	Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2021)
Parts: 143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB2633G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented/Bent	726.00 FN	*726.00 FN
2	1		*REAR BOOT LOGO	Necessary	48.00 FN	*48.00 FN
3	1		*REAR BOOT EMBLEM LANCER	Necessary	32.00 FN	*32.00 FN
4	1		*REAR BOOT EMBLEM SPORT	Not Necessary	36.00 FN	*- FN
5	1		*REAR BOOT EMBLEM GLX	Necessary	32.00 FN	*32.00 FN
6	1		*REAR BOOT LICENCE PLATE GARNISH	Cut/Cracked	197.00 FN	*197.00 FN
7	1		*REAR BOOT INNER LOCK	Twisted	139.00 FN	*139.00 FN
8	2		*REAR BOOT HINGES RH/LH	Serviceable	270.00 FN	*- FN
9	2		*REAR BOOT STOPPER	Not Necessary	21.00 FN	*- FN
10	1		*REAR BOOT W/STRIP	Twisted	136.00 FN	*136.00 FN
11	1		*REAR BUMPER	Distorted	736.00 FN	*727.00 FN
12	1		*REAR BUMPER LOWER SPOILER	Distorted/Torn	1,296.00 FN	*726.00 FN
13	1		*REAR BUMPER BEAM	Bent	165.00 FN	*165.00 FN
14	2		*REAR BUMPER SIDE RETAINERS RH/LH	Bent	110.00 FN	*110.00 FN
15	1		*REAR END PANEL	Dented	435.00 FN	*435.00 FN
16	1		*REAR END PANEL GARNISH	Twisted	132.00 FN	*132.00 FN
17	1		*REAR EXHAUST SILENCER	Repair	497.00 FN	*- FN
18	1		*REAR EXHAUST CHROME PIPE	Not Necessary	126.00 FN	*- FN
19	2		*REAR EXHAUST MOUNTINGS	Not Necessary	56.00 FN	*- FN
20	1		*REAR FLOOR BOARD	Torn	286.00 FN	*286.00 FN
21	1		*REAR FLOOR PANEL	Repair	935.00 FN	*- FN
22	1		*REAR FENDER RH	Repair	835.00 FN	*- FN
23	2		*REAR FENDER CORNER PANEL RH/LH	Repair	330.00 FN	*- FN
24	2		*REAR FENDER INNER TRIMS RH/LH	Deformed/Torn	684.00 FN	*424.00 FN
25	2		*REAR FENDER INNER SHIELDS RH/LH	Not Necessary	136.00 FN	*- FN
26	2		*REAR TAILLAMPS RH/LH	Cracked	972.00 FN	*890.00 FN
27	2		*REAR TAILLAMPS PANELS RH/LH	Repair	310.00 FN	*- FN
28	1		*SET REAR BUMPER REVET PLUG KIT	Necessary	60.00 FS	*50.00 FS
29	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
30	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
31	1		*SET REAR NUMBER PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR BOOT TOP SPOILER CLIP	Not Necessary	80.00 FS	*- FS
33	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	10,668.00	5,515.00
- Nett Item Discount on N Items 10.00/10.00% (\$)	967.80	520.50
Total Parts (\$)	9,700.20	4,994.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	New	80.00	50.00
4	TO TUFF KOTE	New	150.00	60.00
5	TO REMOVE & REPLACE EXHAUST SYSTEM	New	100.00	0.00
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	1,400.00	1,180.00
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	1,500.00	900.00
			Gross Labour Cost (\$\$)	3,400.00
				2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >