



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name /Ms Stephanie Lim Chwee Ang Reg No/Reg Date SMN3831X*KC17P / 05/08/2019 Date In/Mileage 18/11/2021/ 23864 Chassis No KNAF3416MK5045895 Engine No G4FGKH738821 Make/Model KIA/CER1.6AEXG333 Colour/Trim 4SS / WK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000036	Credit	18/11/2021/ 17:52	DS	303 / Renemer	22251				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	ZPCOAT15-M	Nano Graphene Premium Coating (15% Off) - Cat B Veh. Comes with 3 yrs Warranty covers against product bonding failure, blistering, bubbling, cracking, delaminating or peeling during the course of warranty duration from the date of application. T&Cs apply.							427.38
P	WAMBG3018	B2 BODYGUARD GRAPHEN			1.00				
P	WAMBG8034	B2 BODYGUARD MICROFI			1.00				
M	WAMBG1002	B2 BG NANO MIRACLE S			1.00				
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00	
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS						100.00	
S	MIPNT88088	TO REPLACE RH HEADLAMP, LOGO, UPR & LWR FRONT BUMPER CLIPS, BRACKETS, T/SIGNAL LAMP & COVER, ETC						1920.00	
		-TO REPAIR RH FENDER							
		STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS						1650.00	
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS							
M	KS 92102 M6 120	RH LAMP ASSY-HEAD			1.00	1219.00	0.00	1219.00	
M	KS 86318 3R 500	ORNAMENT - KIA NO. 1			1.00	32.00	0.00	32.00	
M	KS 86511 M6 000	UPR COVER - FRONT BU			1.00	633.00	0.00	633.00	
M	KS 86530 M6 000	LWR GRILLE - FRONT B			1.00	262.00	0.00	262.00	
M	KS 06032 50 037A	FASTERNER- BUMPER			10.00	2.00	0.00	20.00	
M	KS 86552 M6 000	RH BRACKET-FR BUMPER			1.00	22.00	0.00	22.00	
M	KS 86551 M6 000	LH BRACKET-FR BUMPER			1.00	22.00	0.00	22.00	
M	KS 86596 M6 000	RH MOULDING-FRONT BU			1.00	36.00	0.00	36.00	
M	KS 92304 M6 000	RH LAMP ASSY - SIDE			1.00	143.00	0.00	143.00	
M	KS 86542 M6 000	RH AIR DUCT-FR BUMPE			1.00	15.00	0.00	15.00	
M	KS 86520 M6 000	ABSORBER-FRONT BUMPE			1.00	84.00	0.00	84.00	
Z	NOTES	ACCIDENT ON 17/11/2021 ALONG BLK 443 SING MING AVENUE CARPARK OWNER CLAIMING THIRD PARTY							

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

## ESTIMATE


Invoice Name & Address	Owner Name & Vehicle Info	
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name	/Ms Stephanie Lim Chwee Ang
Contact No	Reg No/Reg Date	SMN3831X*KC1/ 05/08/2019
	Date In/Mileage	18/11/2021/ 23864
	Chassis No	KNAF3416MK5045895
	Engine No	G4FGKH738821
	Make/Model	KIA/CER1.6AEXG333
	Colour/Trim	4SS / WK

					WIP No
Account No	Terms	Date/Time Printed	CSE	Operator	22251
F0000036	Credit	18/11/2021/ 17:52	DS	303 / Renemer	
Description of Goods / Services					
				Qty	Unit Price
					Disc%
					Amount

REQUIRED REPLACEMENT CAR  
TP#: CB7059P

TP INS: I.I.I

# Estimate



Confirm &amp; accepted by

Parts	2,488.00
Labour	0.00
Standard Menu	427.38
Specialist Job	3,920.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	6,835.38

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.