

Company Reg No: 202136904Z

E-mail: hdperfectautowok@gmail.com



**HD PERFECT
AUTOWORK PTE LTD**

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **PC3485J**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 17.11.2021
TIME OF ACCIDENT : 11:15HRS

KDH 2230022

Xiao Tony

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,054.20	\$ 2,054.20
2	TAILGATE DETECTOR <i>also cracked</i>	1	\$ 289.40	\$ 289.40
3	TAILGATE LOGO <i>new</i>	1	\$ 75.10	\$ 75.10
4	TAILGATE 'HIACE' EMBLEM <i>new</i>	1	\$ 57.40	\$ 57.40
5	TAILGATE CENTER MOULDING (CHROME) <i>cut</i>	1	\$ 467.30	\$ 467.30
6	TAILGATE INNER BOARD (LOWER) <i>new</i>	1	\$ 271.80	\$ 271.80
7	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 329.60	\$ 329.60
8	TAILGATE WEATHERSTRIP PROTECTOR <i>new</i>	1	\$ 178.90	\$ 178.90
9	TAILGATE LOCK OUTER HANDLE <i>new</i>	1	\$ 268.70	\$ 268.70
10	TAILGATE INNER LOCK COVER <i>new</i>	1	\$ 75.40	\$ 75.40
11	TAILGATE INNER LOCK <i>new</i>	1	\$ 475.60	\$ 475.60
12	TAILGATE LOWER LOCK <i>bugd</i>	1	\$ 105.00	\$ 105.00
13	TAILGATE CENTER LOCK MOTOR <i>new</i>	1	\$ 435.70	\$ 435.70
14	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 69.60	\$ 139.20
15	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
16	TAILGATE WINDSCREEN GLASS <i>new</i>	1	\$ 1,249.80	\$ 1,249.80
17	TAIL LAMP <i>LH cracked</i>	2	\$ 374.60	\$ 749.20
18	TAILLAMP LOWER GARNISH <i>LH cracked</i>	2	\$ 110.10	\$ 220.20
19	TAILLAMP LOWER GARNISH RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
20	REAR BUMPER <i>Deformed</i>	1	\$ 395.00	\$ 395.00
21	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.00	\$ 110.00
22	REAR END PANEL (INNER) <i>PG 5</i>	1	\$ 1,043.20	\$ 1,043.20
23	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 542.10	\$ 542.10
24	REAR FLOOR PANEL MAT <i>Not new</i>	1	\$ 1,591.50	\$ 1,591.50
25	REAR SPARE TYRE HOLDER BRACKET <i>2nd</i>	1	\$ 649.30	\$ 649.30
26	REAR SPARE TYRE HOLDER BOLT <i>1st</i>	1	\$ 60.00	\$ 60.00

✓
 ✓ 165
 ✓
 ✓
 ✓
 ✓ 366
 +
 ✓
 +
 +
 +
 +
 +
 ✓
 +
 +
 +
 +
 +
 374.60
 110.10
 +
 ✓
 ✓
 +
 ✓
 4684.10
 X.
 X
 3513.07
 +

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC3485J**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 17.11.2021
 TIME OF ACCIDENT : 11:15HRS

TOTAL PRICE \$ 11,991.60
 LESS 25% \$ 2,997.90
SUB TOTAL PRICE \$ 8,993.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
4	TAILGATE WEATHERSTRIP PROTECTOR COVER (SPECIAL TYPE) <i>Dented</i>	1	\$ 400.00	\$ 400.00
5	TAILGATE CENTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	TAILGATE STICKER 'EMERGENCY DOOR' <i>new</i>	1	\$ 40.00	\$ 40.00
8	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00
9	TAILGATE COMPANY STICKER (SET) <i>new</i>	1	\$ 800.00	\$ 800.00
10	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00
12	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
13	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
14	REAR END PANEL (INNER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
15	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
16	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
17	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00
18	REAR FLOOR PANEL MAT CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
19	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00
20	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00

TOTAL \$ 4,340.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800
3	WIRNING, BULB CHECKING	\$ 80.00	30
4	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
5	TRANSFER TAILGATE MECHAISM	\$ 80.00	✓

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **PC3485J**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 17.11.2021
TIME OF ACCIDENT : 11:15HRS

6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
9	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	X
10	REMOVE AND REFIX REVERSE CAMERA	\$ 80.00	50.
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X.

TOTAL \$4,970.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,333.70
TOTAL LABOUR COST : \$ 4,970.00
TOTAL REPAIR COST : \$ 18,303.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
4/s 29/11/21.
06 Days.

Total: 6418.07
2/s: 5.1K.

1880