



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Ref: CC4/ASM19007614/Kba3q2 Date: 02/12/2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 3098X	Veh. Inspected	SJP 4734L
	Policy No.	GA448528	Coverage (\$)	0.00
	Claim No.	S9M01ILB	Excess (\$)	0.00
	Assign From		Assign Date	30/04/2019
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI AVANTE (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	KMH DU41BR9U724905	Colour	METALLIC MAROON
	Odometer	-	Steering	JAMMED
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	LING LONG	8 mm
	L/H Rear Tyre	195/65 R15	LING LONG	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/03/2019	Inspection Date	30/04/2019
	Survey held at	POON POONG MOTORS PTE LTD BLK 176 SIN MING DRIVE #05-14/15 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	