

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011826/EUF3E2

Date: 24/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070095966
Claimant Vehicle No : SLS3685L Insured Vehicle No : GT8903D
Date of Loss: 17/11/2021 Nature of Claim: TP Claim No: 3433860544SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS3685L**
Make & Model: TOYOTA SIENTA, 1.5 (A) Engine No: 1NZR525081
Reg. Date: 21/09/2017 (Man. Year: 2017) Chassis No: NHP1707091300
Colour: Brown Odometer: 341876 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/11/2021
Date Inspected: 22/11/2021 Inspected At: LAY AUTO GARAGE PTE LTD (HQ)
38 Toh Guan Road East #01-56
Enterprise Hub
Singapore 608581
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$69,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	2		*REAR BUMPER PROTECTOR	Cut	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	* Check	0.00 F	*- F
6	1		*REVERSE SENSOR	Broken	0.00 F	*- F
7	1		*BOOTLID LOCK	* Check	0.00 F	*- F
8	1		*TAILGATE	Dented	0.00 F	*- F
9	2		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >