

TPAxA

SSS9580P · 2009 Sept.

Veron.

Kia Cerato Forte

1591cc

KN1AFW411MAS116204

Front Bumper	Deformed	545.30 ✓
Front Bumper Clips	new	30(SN). ✓
Front Bumper Side Holder x 02	and	23 x 2 = 46. ✓
Front Bumper lower Spoiler	torn	850(SN) 600(SN)
Front Bumper Sponge	cracked	112 ✓
Front Bumper Undercover	torn	115.40. ✓
Front Bumper Undercover Clips.	new	20(SN) ✓
Front Bumper Fog Lamp RH.	2	286.90. x
Front Bumper Fog Lamp Cover RH	new	72.10. x
Front Bumper lower Grille.	new	127.20 x
Front Grille	cracked	265 ✓
Front Grille Clips.	new	20(SN) ✓
Headlamp RH.	cracked	588.60 ✓
Headlamp lower Bracket RH	new	32.50 x

SJS9580P.

Front Support Panel. xrl m 688.20 +
Wiper Washer Tank. cruld 125.30. ✓

1297.60 S.N: 670

1617.84

Panel Beating

Spry Painting.

Wiring.

To remove condenser and }
to top up air con gas 1.

To remove radiator and }
to top up coolant 1.

~~800~~ 400

~~600~~ 400

~~50~~ 30

120 +

120 +

5614.50

total: 3117.84

L/S: 2.HK

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Approved by Repairer