



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21011838/R1uce2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 17-12-2021
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | YP 2498D | Veh. Inspected | SMB 11D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1154669-001 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 19/11/2021 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------------------|--------------|----------|
| Make & Model | MERCEDES BENZ OC500LE1830H | c.c | 11967 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | WEB63442021000068 | Colour | GREEN |
| Odometer | 962187 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------------|---------|---------|
| R/H Front Tyre | 275/70 R22.5 | FIRENZA | 8 mm |
| L/H Front Tyre | 275/70 R22.5 | FIRENZA | 8 mm |
| R/H Rear Tyre | 275/70 R22.5 (D) | FIRENZA | 8/8 mm |
| L/H Rear Tyre | 275/70 R22.5 (D) | FIRENZA | 8/8 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 15/11/2021 | Inspection Date | 19/11/2021 |
| Survey held at | STRIDES AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 1 Working Days |
|-------------------------------------|----------------|