

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011842/DQF3E2

**Date:** 18/05/2022

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001227830

**Claimant Vehicle No :** SJC1036G

**Insured Vehicle No :** SFQ945M

Date of Loss: 19/11/2021

Nature of Claim: TP

Claim No: 265651

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC1036G**

Make & Model: SUZUKI SWIFT, 1.3 XG (M)

Engine No: M13A1993012

Reg. Date: 30/01/2008 (Man. Year: 2007)

Chassis No: ZC11S401473

Colour: Black

Odometer: 323899 km

Engine Capacity: 1328 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,697.39	2,102.57	17,594.82	89.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,120.00	1,450.00	4,670.00	76.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,817.39</b>	<b>3,552.57</b>	<b>22,264.82</b>	<b>86.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,800.00</b>		
<b>(S\$)</b>	25,817.39	2,800.00	23,017.39	89.15
<b>+ GST 7.00/7.00% (S\$)</b>	1,807.22	196.00	1,611.22	89.15
<b>Nett Amount (S\$)</b>	<b>27,624.61</b>	<b>2,996.00</b>	<b>24,628.61</b>	<b>89.15</b>

### INSPECTION

Date of Assignment: 22/11/2021

Date Inspected: 22/11/2021 Inspected At:

JWG International Pte Ltd (HQ)  
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK  
AutoPoint  
Singapore 568047

Estimated Period of Repair: 4.0 days

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2022)
<b>Parts:</b>	144	SUZUKI SWIFT 1.3 XG (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJC1036G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,628.15 FL	*628.10 FL
2	1		*TAILGATE WIPER MOTOR	Not Necessary	318.30 FL	*- FL
3	1		*TAILGATE WIPER ARM	Not Necessary	105.35 FL	*- FL
4	1		*TAILGATE WINDSCREEN MOULDING	Necessary	335.40 FL	*68.10 FL
5	1		*TAILGATE SWITCH	Not Necessary	188.46 FL	*- FL
6	1		*TAILGATE LOCK	Not Necessary	319.10 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	743.80 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Serviceable	212.65 FL	*- FL
9	1		*TAILGATE LOGO	Necessary	94.00 FL	*52.00 FL
10	1		*TAILGATE SWIFT EMBLEM	Necessary	99.00 FL	*56.00 FL
11	4		*TAILGATE RUBBER STOPPER	Not Necessary	79.20 FL	*- FL
12	1		*TAIL LAMP L+R	O/S MtgCracked/N/SNotNecessary	1,253.30 FL	*287.90 FL
13	2		*TAIL LAMP PANEL L+R	Not Necessary	599.74 FL	*- FL
14	2		*TAIL LAMP BRACKET L+R	Not Necessary	318.00 FL	*- FL
15	1		*REAR BUMPER	Distorted	859.65 FL	*549.65 FL
16	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	153.46 FL	*- FL
17	2		*REAR NO PLATE LAMP L+R	Not Necessary	161.50 FL	*- FL
18	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	184.38 FL	*- FL
19	1		*REAR END PANEL	Repair	1,075.85 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Serviceable	302.74 FL	*- FL
21	1		*SPARE WHEEL PANEL	Not Necessary	1,475.20 FL	*- FL
22	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	419.48 FL	*- FL
23	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	788.58 FL	*- FL
24	1		*SPARE WHEEL TOOL BOX	Not Necessary	401.93 FL	*- FL
25	2		*REAR FENDER L+R	Not Necessary	3,578.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,964.00 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	105.29 FL	*- FL
28	1		*REAR EXHAUST MOUNTING	Not Necessary	99.26 FL	*- FL
29	1		*REAR NUMBER PLATE	Bent	100.00 FS	*45.00 FS
30	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
32	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS
33	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
37	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR EXHAUST PIPE (LOCAL REPAIR)	Bent	2,000.00 FS	*300.00 FS
39	1		*REVERSE CAMERA	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,483.77</b>	<b>2,266.75</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>1,786.38</b>	<b>164.18</b>
<b>Total Parts (\$\$)</b>	<b>19,697.39</b>	<b>2,102.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	60.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	40.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
7	TO RNR REAR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	300.00	0.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,120.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >