#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Nor Azian Binte Noordin Date: 22 Apr 2022

# **Preliminary Advice**

Insured : SFQ945M

Vehicle No

No

TP Vehicle

: SJC1036G

Accident Date

: 19/11/2021

Make : SUZUKI SWIFT Assignment Date: 22/11/2021

Date of : 22/11/2021 Est. Duration of

• 4 Inspection Repair

Inspection At: JWG INTERNATIONAL PTE LTD (HQ)

BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK

**AUTOPOINT** 

SINGAPORE 568047

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 25,817.39 Revised Amount :S\$ 3,552.58 Check Items (Estimated) :S\$ 0.00

Total :S\$ 3,552.58

Lump Sum Repair :S\$ 2.800.00

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 8,000.00

COE / PARF Rebate :S	3\$	,499.00
----------------------	-----	---------

Salvage Value :S\$

Margin for Repair :S\$ 4,501.00

### Remarks

(	)	The vehicle is economical for repair
(	)	The vehicle is not economical for repair
(	)	Part-by-Part repair
<b>( )</b>	()	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject toconsistency check, part prices and labour cost.