And the second s	
CS MSG 2	1011842 Dats
	COE Jen 2023
PIDITE Date:	Van No. SJC 1036 G YT REGIL 2008 Jan =
Estimate Cost	Type/M.Car / M.Cycle / Bos / Van / Lony / Tax / Prime Mover /
OF THE THEFT PRESIDERES / EVA / HAV / WAV	Truck/Traffer or
To Inspatible No:	Note: Suzuki Swift CE 1328
五 格 一	Colour Blade AG Insured Still MA
isf	
insued	Sp. Reading 323899 T.Radin: Insured Still 1811
Policy EL	Eng/No: - M13A1993012
	ZC11S401473 =
200001	Sen. Cond. Good Fair / Poor / Burní
(Checkbecom) - Excess	Siesting: in Order / Januared / Leaked / Burni or
Make Civiti	Brake: horder Januari Leaked Burni or
	Mod: HE SATE STD ARTE OF
(Policy Condition)	Tyre State: F. 195 55 7215
Rent at ETHE veh had commenced its N/S O/S	R U
ispair at the fine of inspection.	BEIDIMIENMONTIEN LEIFTY ME I DHLEN LAE I 2020
Bal or Marier Value:	FIDIL REEL REEL
- IDAC Amilianti Rport Consistent? : Yes or No	R/Bal C man R/Bal C man
GIA / PR Seem Consistent? : Yes of No	LBal S IIII
Est Repairs 4" days Res.: Yes or No	D.D.A. 19 11/221 D.D.I. 22/11/221
Lingston 20 % 3 Val.: Yes or No	Survey held at JWG AMIC
CA / REV / REP. / 24 HRS	Des of Damages: Fri Rear O/S HUS U/C Rootiop or
Dafe:Person Confeded: Vehicle: IN / O	UT 1Cm
Daie /Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
MSIG SPQ 945M	
22/04/22@12.05pm revised & email Nor Azia	n to seek mandate at LS \$2800, 4 days.
MV 8K	
LIA 3.5K	
HV 4.5K.	a proceed with our auryover's recommendation if the
damages are consistent and repair cost is in	e proceed with our surveyor's recommendation if the order and within repair limit.
Bryan finalised LS \$2800, 4 days. (
Prefit Report	Days Of Repair: 4
22/04 Typist	Resurvey No. of Trip: 1 Survey Fee:
Date/Tane, File Return to?	Transportations
Acid	Fee: Site Insp (\$ 1_8+RS_SI

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SFQ945M [YOUR INSURED] & SJC1036G [OUR CLIENT] ON 19/11/2021.

ESTIMATED REPAIR COSTS FOR SJC1036G

QTY	<u>PARTS</u>	AMOUNT	
1PC	TAILGATE Devol 628.10	\$ 1,628-15	1-
1PC	TAILGATE WIPER MOTOR H-4	\$ 318.30	X
1PC	TAILGATE WIPER ARM	\$ 105.35	×
1PC	TAILGATE WINDSCREEN MOULDING 400	\$ 335.40	1
1PC	TAILGATE SWITCH HH	\$ 188.46	×
1PC	TAILGATE LOCK HH	\$ 319.10	X
1PC	TAILGATE INNER TRIM BOARD HIM	\$ 743.80	X
1PC	TAILGATE WEATHER STRIP Sv.	\$ 212.65	×
1PC	TAILGATE LOGO HLL 52-W	\$ 94.00	1
1PC	TAILGATE SWIFT EMBLEM HIL 56.00	\$ 99.00	1
4PC	TAILGATE RUBBER STOPPER @ \$19.80 EACH	\$ 79.20	X
2PC	TAIL LAMP L+R @ \$626.65 EACH 0 3 money and 4/5H 287-90	\$ 1,253.30	سليا
2PC	TAIL LAMP PANEL L+R @ \$299.87 EACH	\$ 599.74	X
2PC	TAIL LAMP BRACKET L+R @ \$159.00 EACH ►	\$ 318.00	X
1PC	REAR BUMPER district 549-65	\$ 859.65	1
2PC	REAR BUMPER SIDE RETAINER L+R @ \$76.73 EACH	\$ 153.46	X
2PC	REAR NO. PLATE LAMP L+R @ \$80.75 EACH	\$ 161.50	
2PC	REAR BUMPER BRACKET LH / RH @ \$92.19 EACH →	\$ 184.38	
1PC	REAR END PANEL	\$ 1,075.85	×
1PC	REAR END PANEL TOP GARNISH SYL	\$ 302.74	X
1PC	SPARE WHEEL PANEL MA	\$ 1,475.20	×
1PC	SPARE WHEEL PANEL TOP BOARD	\$ 419.48	X
2PC	SPARE WHEEL QUARTER PANEL LH / RH @ \$394.29 EACH	\$ 788.58	X
1PC	SPARE WHEEL TOOL BOX HA	\$ 401.93	X
2PC	REAR FENDER L+R @ \$1,789.00 EACH	\$ 3,578.00	X
2PC	REAR FENDER INNER TRIM L+R @ \$982.00 EACH ►	\$ 1,964.00	X
1PC	REAR EXHAUST HEAT SHIELD HH	\$ 105.29	×
1PC	REAR EXHAUST MOUNTING HA	\$ 99.26	X

PARTS SUM: \$ 17,863.77

PARTS LESS 10%: \$ 1,786.38

1641-75

LABOUR & SPECIAL NETT ITEMS

			45/
*	TO SUPPLY REAR NUMBER PLATE ゆ	S	100.00 45
*	TO SUPPLY TAILGATE INNER TRIM CLIPS HH	S	50.00 ×
*	TO SUPPLY REAR BUMPER CLIPS - LLC	S	50.00 201-
*	TO SUPPLY 1 SET REVERSE SENSOR D. W	\$	300.00 2201-
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS	S	50.00 ×
*	TO SUPPLY REAR END PANEL SEALANT HA	\$	80.00 ×
*	TO SUPPLY REAR WINDSCREEN SEALANT NEC	\$	80.00 461
*	TO SUPPLY REAR WINDSCREEN DAMPING SEAL HA	\$	30.00 ×
*	TO SUPPLY SPARE WHEEL PANEL SEALANT HA	\$	80.00 ×
*	TO SUPPLY REAR EXHAUST PIPE LLZOO 625.00	\$	2,000.00 Rent
*	TO SUPPLY REVERSE CAMERA HH	\$	800.00 ×
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE	\$	300.00 61-
	REPAIRS		0
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	2,000.00 500 -
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00 600 -
*	TO TUFF COAT DAMAGED AREAS	\$	200.00 40 -
*	TO RNR REVERSE CAMERA	\$	100.00 ⊢
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$	400.00 1201-
*	TO RNR REAR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$	200.00 601
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$	300.00 HH
	TO CHECK & BE EIV ALL ELECTRICAL WIRDINGS (450-W)	Ψ	300.00 PH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00 30 -
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00 ₩₩
*	TO RNR REVERSE SENSOR TO FACILITATE REPAIRS	\$	120.00 40]-
			l l

LABOUR & S/N TOTAL: \$ 9,740.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 25,817.39

22/11/2021 @ 1708hs 3552.48

Not Andrew 4/52,800/2/2hm
2/3hm
2/4 days.

Checkpart

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: