

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011843/BVF3E2

**Date:** 06/06/2022

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001858017

**Claimant Vehicle No :** SKN1609J

**Insured Vehicle No :** GBL5152A

Date of Loss: 17/11/2021

Nature of Claim: TP

Claim No: 265585

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN1609J**

Make & Model: HONDA FIT SHUTTLE, 1.5 (A)

Engine No: L15A7106597

Reg. Date: 19/05/2014 (Man. Year: 2013)

Chassis No: GG73104763

Colour: Grey

Odometer: 140692 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,226.76	2,738.28	5,488.48	66.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,000.00	1,780.00	47.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,006.76</b>	<b>4,738.28</b>	<b>7,268.48</b>	<b>60.54</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,790.00</b>		
<b>(S\$)</b>	12,006.76	3,790.00	8,216.76	68.43
<b>+ GST 7.00/7.00% (S\$)</b>	840.47	265.30	575.17	68.43
<b>Nett Amount (S\$)</b>	<b>12,847.23</b>	<b>4,055.30</b>	<b>8,791.93</b>	<b>68.43</b>

### INSPECTION

Date of Assignment: 22/11/2021

Date Inspected: 22/11/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** Lim Teow Guan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Jun 2022)	
<b>Parts:</b>	N/A	HONDA FIT SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN1609J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	890.20 FL	*890.20 FL
2	1		*TAILGATE CENTRE EMBLEM	Necessary	65.50 FL	*53.00 FL
3	1		*TAILGATE FIT SHUTTLE EMBLEM	Necessary	66.10 FL	*55.00 FL
4	1		*TAILGATE WINDSCREEN GLASS RUBBER SEAL	Necessary	164.30 FL	*164.30 FL
5	1		*TAILGATE CHROME MOULDING	Necessary	321.20 FL	*110.35 FL
6	1		*TAILGATE REVERSE CAMERA	Not Damaged	608.20 FL	*- FL
7	1		*TAILGATE WIPER MOTOR	Not Damaged	589.70 FL	*- FL
8	1		*TAILGATE WIPER ARM	Not Damaged	81.20 FL	*- FL
9	1		*TAILGATE LOCK	Not Damaged	113.50 FL	*- FL
10	1		*TAILGATE LOCK CATCH	Not Damaged	24.70 FL	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Not Necessary	145.20 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Not Necessary	101.40 FL	*- FL
13	1		*REAR BUMPER	Dented	780.20 FL	*510.00 FL
14	1		*REAR BUMPER RH REFLECTOR	Not Damaged	78.30 FL	*- FL
15	1		*REAR BUMPER LH REFLECTOR	Not Damaged	78.30 FL	*- FL
16	1		*REAR BUMPER RH SIDE RETAINER	Necessary	64.70 FL	*28.60 FL
17	1		*REAR BUMPER LH SIDE RETAINER	Necessary	64.70 FL	*28.60 FL
18	1		*REAR BUMPER RH INNER SPONGE	No such part	92.30 FL	*- FL
19	1		*REAR BUMPER LH INNER SPONGE	No such part	92.30 FL	*- FL
20	1		*RH TAILLAMP ASSY	Broken	680.40 FL	*435.20 FL
21	1		*RH TAILLAMP SPONGE GASKET	Necessary	21.20 FL	*21.20 FL
22	1		*LH TAILLAMP ASSY	Not Necessary	680.40 FL	*- FL
23	1		*LH TAILLAMP SPONGE GASKET	Not Necessary	21.20 FL	*- FL
24	1		*END PANEL	Dented	455.60 FL	*455.60 FL
25	1		*END PANEL INNER GARNISH	Broken	95.80 FL	*95.80 FL
26	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	490.50 FL	*- FL
27	1		*REAR LH FENDER	Repair	980.40 FL	*- FL
28	1		*REAR LH FENDER INNER TRIM BOARD	Not Necessary	490.50 FL	*- FL
29	1		*REAR COMPARTMENT PANEL TOP BOARD	Not Damaged	589.20 FL	*- FL
30	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*30.00 FS
31	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
32	1		*TAILGATE ONE STICKER	Necessary	30.00 FS	*30.00 FS
33	1		*TAILGATE GARAGE & COLOUR STICKER	Necessary	55.00 FS	*30.00 FS
34	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS
37	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
38	1		*END PANEL JOINT SEALANT	Necessary	60.00 FS	*30.00 FS
39	1		*SET REAR RH FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*20.00 FS
40	1		*SET REAR LH FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*20.00 FS
41	1		*REAR LH FENDER JOINT SEALANT	Not Necessary	60.00 FS	*- FS
42	1		*REAR LH FENDER GLASS SEALANT	Not Necessary	70.00 FS	*- FS
43	1		*REAR LH FENDER GLASS INNER SEAL	Not Necessary	40.00 FS	*- FS
44	1		*REAR NUMBER PLATE	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 10,012.20 3,307.85

Report was unsubmitted during this print-out.



Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,400.00	800.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,200.00	800.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	100.00	0.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER COMPONENTS TO ASSIST REPAIR	New	120.00	80.00
7	REMOVE, REPLACE AND ADJUST TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	0.00
8	REMOVE AND REPLACE REAR INNER TRIM, GARNISH, ROOF LINING, SEATS AND CARPET TO ASSIST REPAIR	New	250.00	80.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	60.00
10	REMOVE AND REINSTALL REAR LH FENDER GLASS TO ASSIST REPAIR	New	120.00	0.00
11	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	70.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,780.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >