

ASS. REC. BY: TCM

REF:

CS/MSG210/1843/BVf3Version

ASSIGNMENT

From:

Date: 22/11/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 1609Jat Workshop m/s Bifrost Autoof 8 Keki Bt Ave 4 Premier #01-49

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

36000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKN 1609JYr Regn: 19/5/2014Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit Shuttlec.c 1497

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

140 692

T/Radio: Insured / Std / NI / NA

Eng/No:

L15A7106597

C/No:

GG73104763

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/60/15R: 185/60/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

17/11/2021

D.O.I.

22/11/2021

Survey held at

Bifrost Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: 5000/- - 6000/-Recommended CAR: LS \$ 5050/-Remain RM for fuelMV 36,000/-11/5/22PV 19,484/-NV 16,516/-TCM16/4/2022

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.S. / C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Grey

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: SKN1609J
Model and make: Honda fit Shuttle
Chassis: GG73104763

Qty Spare parts

List price 2014

1	Tailgate	\$	✓ 890.20	DDV
1	Tailgate centre emblem	\$	53.00 -65.50	NECV
1	Tailgate "FIT SHUTTLE" emblem	\$	55.00 -66.10	NECV
1	Tailgate windscreen glass rubber seal	\$	✓ 164.30	NECV
1	Tailgate chrome moulding	\$	110.35 -321.20	NDX
1	Tailgate reverse camera	\$	608.20	NDX
1	Tailgate wiper motor	\$	589.70	NDX
1	Tailgate wiper arm	\$	-81.20	NDX
1	Tailgate lock	\$	113.50	NDX
1	Tailgate lock catch	\$	-24.70	NDX
1	Tailgate inner trim board	\$	✓ 145.20	BRV
1	Tailgate weatherstrip	\$	✓ 101.40	TNV
1	Rear bumper	\$	510.00 780.20	DDV
1	Rear bumper RH reflector	\$	78.30	NDX
1	Rear bumper LH reflector	\$	78.30	NDX
1	Rear bumper RH side retainer	\$	28.60 64.70	NECV
1	Rear bumper LH side retainer	\$	28.60 64.70	NECV
1	Rear bumper RH inner sponge	\$	92.30	NSX
1	Rear bumper LH inner sponge	\$	92.30	NSX
1	RH taillamp assy	\$	435.20 680.40	BRV
1	RH taillamp sponge gasket	\$	✓ 21.20	NECV
1	LH taillamp assy	\$	680.40	NSX
1	LH taillamp sponge gasket	\$	21.20	NSX
1	End panel	\$	✓ 455.60	DDV
1	End panel inner garnish	\$	✓ 95.80	BRV
1	Rear RH fender inner trim board	\$	394.10 490.50	BRV
1	Rear LH fender + 1m	\$	912.40 -980.40	DDV
1	Rear LH fender inner trim board	\$	394.10 490.50	BRV
1	Rear compartment panel top board	\$	589.20	NDX

\$ 4795.05 8,927.20
-20% \$ 959.01 1,785.44
\$ 3836.04 7,141.76

Qty Spare parts

Special Nett

1	Tailgate windscreen glass sealant	\$	30.00 -70.00	NECV
1	Tailgate windscreen glass inner seal	\$	20.00 -50.00	NECV
1	Tailgate "One" sticker	\$	✓ 30.00	NECV
1	Tailgate "Garage & Colour" sticker	\$	30.00 55.00	NECV

1set Tailgate inner trim board clips
 1set Rear bumper clips
 1set Rear bumper reverse sensor
 1set End panel inner garnish clips
 1 End panel joint sealant
 1set Rear RH fender inner trim board clips
 1set Rear LH fender inner trim board clips
 1 Rear LH fender joint sealant
 1 Rear LH fender glass sealant
 1 Rear LH fender glass inner seal
 1 Rear number plate

\$	30.00	60.00	NECV
\$	30.00	70.00	NECV
\$	200.00	280.00	SCV
\$	20.00	40.00	NECV
\$	30.00	60.00	NECV
\$	20.00	60.00	NECV
\$	20.00	60.00	NECV
\$		60.00	NECV
\$		70.00	NNX
\$		40.00	NNX
\$		80.00	NNX
\$	460.00		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
 To panel beating, cut / weld and re-align all affected panels

\$ 800.00 1,400.00 ✓

Spray painting on affected panels

\$ 800.00 1,200.00 ✓

Check wiring and lighting system

\$ 100.00 NNX

Apply rust coating chemical on affected panels

\$ 100.00 NNX

Remove and reinstall tailgate windscreen glass to assist repair

\$ 120.00 220.00 ✓

Remove and replace tailgate inner components to assist repair

\$ 80.00 120.00 ✓

Remove, replace and adjust tailgate reverse camera to assist repair

\$ 100.00 NNX

Remove and replace rear inner trim, garnish, roof lining, seats and carpet to assist repair

\$ 80.00 250.00 ✓

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 100.00 ✓

Remove and reinstall rear LH fender glass to assist repair

\$ 120.00 NNX

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 70.00 ✓

Final amount \$ 2,600.00 12,006.76

Survey & Resurvey
 22/11/2021
 1208 hrs.
 TGM

Lump Sum repair
 Repair days 6

Parts	3836.04
SN	460.00
Labour	2000.00
	6296.04
@20%	1259.21
	5036.83

LS 5050/2

TGM
 17/4/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: