

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011847/RPA3Q2**Date:** 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100354489-08
<b>Claimant Vehicle No :</b>	SMC8778S	<b>Insured Vehicle No :</b>	SKM1500T
Date of Loss:	29/10/2021	Nature of Claim:	TP
		Claim No:	7111545229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMC8778S</b>	Engine No:	P520453446
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0161126
Reg. Date:	12/07/2017 (Man. Year: 2017)	Odometer:	25622 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,389.44	2,584.24	5,805.20	69.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	2,200.00	650.00	22.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,239.44</b>	<b>4,784.24</b>	<b>6,455.20</b>	<b>57.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>(S\$)</b>	11,239.44	3,800.00	7,439.44	66.19
<b>+ GST 7.00/7.00% (S\$)</b>	786.76	266.00	520.76	66.19
<b>Nett Amount (S\$)</b>	<b>12,026.20</b>	<b>4,066.00</b>	<b>7,960.20</b>	<b>66.19</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	22/11/2021	
Date Inspected:	24/11/2021	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	808.70 FL	*- FL
2	1		*FRONT GRILLE CHROME RH	Not Necessary	329.10 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	293.40 FL	*- FL
4	1		*FRONT HEADLAMP RH	Scratched	2,855.80 FL	*2,855.80 FL
5	1		*FRONT APRON PANEL	Not Necessary	380.90 FL	*- FL
6	1		*FRONT BONNET	Repair	790.90 FL	*- FL
7	1		*FRONT FENDER RH	Repair	292.30 FL	*- FL
8	1		*FRONT DOOR RH	Repair	850.20 FL	*- FL
9	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	212.50 FL	*- FL
10	1		*REAR DOOR RH	Repair	991.90 FL	*- FL
11	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	212.50 FL	*- FL
12	1		*FRONT DOOR SIDE MIRROR RH	Scratched	374.50 FL	*374.50 FL
13	1		*FRONT DOOR SIDE MIRROR COVER RH	Repair	181.20 FL	*- FL
14	1		*FRONT WINDSCREEN PILLAR RH (NPA)	Repair	0.00 FL	*- FL
15	1		*REAR FENDER (RH)	Repair	884.60 FL	*- FL
16	1		*REAR BUMPER	Repair	680.10 FL	*- FL
17	1		*ROCKER PANEL GARNISH RH	Repair	348.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,486.80</b>	<b>3,230.30</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,097.36	646.06
<b>Total Parts (\$)</b>	<b>8,389.44</b>	<b>2,584.24</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	50.00	0.00
2	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	600.00
3	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS ,CLEANING & SANDINF OF SURFACES ,FINAL POLISING & WAXING ARE ALSO AVAILABLE	New	1,800.00	1,600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,850.00</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >