



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01 AXA TOWER  
SINGAPORE 068811  
ATTN: OH VALE

Ref: CS3/ASM21011849/Bty3e2  
Date: 02/12/2021  
Code: ASM

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	SHA 8755C	<b>Veh. Inspected</b>	SJX 7942R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M03MKZ	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	OH VALE	<b>Assign Date</b>	22/11/2021


### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HYUNDAI AVANTE	<b>c.c</b>	1591
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	KMHDU41BMAU020245	<b>Colour</b>	RED
<b>Odometer</b>	172473 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/65 R15	WINDFORCE	6 mm
<b>L/H Front Tyre</b>	185/65 R15	WINDFORCE	6 mm
<b>R/H Rear Tyre</b>	185/65 R15	WINDFORCE	6 mm
<b>L/H Rear Tyre</b>	185/65 R15	WINDFORCE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.	
---	---

### 5. General Information

<b>Accident Date</b>	20/11/2021	<b>Inspect Date / Time</b>	22/11/2021 ( 01:50 PM )
<b>Survey held at</b>	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------

Report Ref No. CS3/ASM21011849/Bty3e2

#### Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.