

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011851/AGA3Q2**Date:** 28/03/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SNA3352T	Insured Vehicle No :	SLN3785H
Date of Loss:	20/11/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0005087

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA3352T	Engine No:	L15B6051531
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82201256
Reg. Date:	17/06/2021 (Man. Year: 2021)	Odometer:	8394 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,600.00	5,791.84	8,808.16	60.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,270.00	1,950.00	4,320.00	68.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,870.00	7,741.84	13,128.16	62.90
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	20,870.00	6,100.00	14,770.00	70.77
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,936.45		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment:	22/11/2021	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	23/11/2021 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA3352T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.60 FL	*1,150.60 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	119.60 FL	*- FL
3	1		*REAR BUMPER MOULDING (CHROME)	Necessary	241.30 FL	*241.30 FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	25.10 FL	*- FL
5	2		*REAR BUMPER SIDE INNER GARNISH	Not Necessary	196.80 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	65.20 FL	*- FL
7	2		*REAR BUMPER SPONGE	Cracked	139.60 FL	*139.60 FL
8	1		*TAIL GATE	Dented	1,342.40 FL	*1,193.00 FL
9	1		*TAIL GATE OUTER GARNISH C/W MOULDING (CHROME)	Cracked	685.10 FL	*383.00 FL
10	1		*TAIL GATE EMBLEM SHUTTLE	Necessary	55.70 FL	*55.70 FL
11	2		*TAIL GATE LAMP	Cracked	841.60 FL	*841.60 FL
12	2		*TAIL GATE STOPPER	Not Necessary	38.00 FL	*- FL
13	1		*TAIL GATE INNER LOCK	Damaged	287.60 FL	*287.60 FL
14	1		*TAIL GATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
15	1		*TAIL GATE WEATHERSTRIP	Cut	179.40 FL	*179.40 FL
16	1		*TAIL GATE INNER TRIM	Cracked	320.90 FL	*320.90 FL
17	1		*TAIL GATE DETECTOR	Not Necessary	128.30 FL	*- FL
18	1		*TAIL GATE DETECTOR WIRE HARNESS	Not Necessary	436.40 FL	*- FL
19	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	150.10 FL	*150.10 FL
20	2		*TAIL LAMP	Not Necessary	1,101.00 FL	*- FL
21	2		*TAIL LAMP LOWER PANEL	Repair	470.40 FL	*- FL
22	1		*REAR REVERSE CAMERA	Not Necessary	1,150.20 FL	*- FL
23	1		*REAR FENDER INNER TRIM	O/S Cracked	978.40 FL	*489.20 FL
24	1		*REAR END PANEL	Dented	685.10 FL	*685.10 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	188.50 FL	*188.50 FL
26	1		*REAR FLOOR PANEL	Repair	986.60 FL	*- FL
27	1		*REAR FLOOR PANEL TOP OUTER BOARD	Not Necessary	585.40 FL	*- FL
28	1		*REAR STORAGE BOX (PLASTIC)	Cracked	396.70 FL	*396.70 FL
29	1		*REAR TOOLS SPONGE TRAY	Not Necessary	216.80 FL	*- FL
30	1		*REAR JACK COVER GARNISH	Not Necessary	124.60 FL	*- FL
31	1		*REAR JACK	Not Necessary	145.00 FL	*- FL
32	1		*REAR BUZZER	Not Necessary	86.10 FL	*- FL
33	1		*CENTRE EXHAUST	Not Necessary	1,260.00 FL	*- FL
34	1		*CENTRE EXHAUST INSULATOR	Not Necessary	85.00 FL	*- FL
35	1		*SET CENTRE EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
36	1		*REAR EXHAUST PIPE	Not Necessary	745.00 FL	*- FL
37	1		*REAR EXHAUST INSULATOR	Not Necessary	195.00 FL	*- FL
38	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
39	4		*REAR EXHAUST MOUNTING	Not Necessary	340.00 FL	*- FL
40	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
41	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
42	1		*SET REAR BUMPER SIDE INNER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
43	1		*SET TAIL GATE OUTER GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
44	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
45	1		*TAIL GATE SIDE LINE (SPECIAL TYPE)	Not Necessary	150.00 FS	*- FS
46	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

3/28/22, 11:51 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
48	1		*SET TAILLAMP CLIP	Necessary	60.00 FS	*20.00 FS
49	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
50	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
51	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
52	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
53	1		*SET REAR JACK COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
54	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,857.50	7,132.30
- List Item Discount on L Items 20.00/20.00% (\$\$)					3,257.50	1,340.46
Total Parts (\$\$)					14,600.00	5,791.84
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,200.00	800.00
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
5	REMOVE AND REFIX VIDEO FOOTAGE	New	150.00	50.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	100.00	0.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	SPECIAL COATING	New	350.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			6,270.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >