4/19/22, 10:59 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21011856/R1EA3Q2

19/04/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900000818 **Claimant Vehicle**

SG6111L Insured Vehicle No: SMG9509A No:

Date of Loss: 03/11/2021 Nature of Claim: TP Claim No: 5929132680SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SG6111L

Make & Model: 50352142135208 MAN A95, 10.5 D (A) Engine No: Reg. Date: 13/06/2019 (Man. Year: 2018) Chassis No: WMAA95ZZ4KF008873

Odometer: 131304 km Colour: Green

Engine Capacity: 10518 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 275/70 R22.5 (D) Rear Tyre Size: Front Left Side: Falken 8 mm Rear Left Side: Falken 8/8 mm Front Right Side: Falken 8 mm Rear Right Side: Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		974.70	0.00	974.70	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,146.00	619.00	527.00	45.99
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	2,120.70	619.00	1,501.70	70.81
		000000000000000000000000000000000000000	252.22		

+ Loss of Use (2.0 x S\$325.00/day) (S\$) 650.00 + Doc/Search Fee (S\$) 7.00 **Nett Liability (S\$)** 1,276.00

INSPECTION

Date of Assignment: 19/11/2021

Strides Automotive Services Pte Ltd (Woodlands) Date Inspected: 19/11/2021 Inspected At:

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: MOHD RASUL Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount		
1 1 F=Franchise part.	*O/S HEADLAMP COVER	Repair	974.70 F	*- F		
		Total Parts (S\$)	974.70	0.00		
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	530.00	265.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	616.00	354.00
	Gross Labour Cost (S\$)		1,146.00	619.00
	Report was unsubmitted during the	is print-out.		

< END OF ESTIMATES >