

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011859/RES3Q2**Date:** 15/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0003221
Claimant Vehicle No : SKF1551H **Insured Vehicle No :** FBR9153P
 Date of Loss: 04/09/2021 Nature of Claim: TP Claim No: MFL2021D0003920

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKF1551H**
 Make & Model: BMW 116I, 1.6 (A) Engine No: A529J168N13B16A
 Reg. Date: 30/04/2012 (Man. Year: 2012) Chassis No: WBA1A12020E951157
 Colour: Blue Odometer: 75868 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,532.80	90.05	2,442.75	96.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,415.00	7,356.00	1,059.00	12.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,947.80	7,446.05	3,501.75	31.99
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	10,947.80	3,000.00	7,947.80	72.60
+ GST 7.00/7.00% (S\$)	766.35	210.00	556.35	72.60
Nett Amount (S\$)	11,714.15	3,210.00	8,504.15	72.60
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,817.45		

INSPECTION

Date of Assignment: 22/11/2021
 Date Inspected: 23/11/2021 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941
 Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$20,000

LTA REBATE: \$16,673

NETT VALUE: \$3,327

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2022)
Parts:	144	BMW 116I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF1551H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR LH DOOR	Repair	1,088.15 FS	*- FS
2	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	127.90 FS	*- FS
3	1		*REAR BUMPER PRIMED (LINES)	Repair	971.50 FS	*- FS
4	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	59.20 FS	*- FS
5	1		*FRT LH DOOR CHANNEL SEALING	Not Necessary	72.95 FS	*- FS
6	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
7	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
8	3		*SECURING PIN	Necessary	10.05 FS	*10.05 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,532.80	90.05
--------------------------	-----------------	--------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,REAR LEFT DOOR INCLUDING TO KNOCK OUT REAR LEFT FENDER AND DENTED AREA CAUSED BY THE ACCIDENT	New	4,250.00	3,400.00
2	TO RESPRAY REAR BUMPER ,LEFT FRONT DOOR ,LEFT REAR DOOR AND LEFT REAR FENDER	New	3,693.00	3,508.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
4	TO CONDUCT CHECK ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	168.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (\$\$)			8,415.00	7,356.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >