

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011861/T1PA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100333059-08
<b>Claimant Vehicle No :</b>	SHD4777A	<b>Insured Vehicle No :</b>	SKJ2477L
Date of Loss:	21/11/2021	Nature of Claim:	TP
		Claim No:	6752835264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD4777A</b>		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU402826
Reg. Date:	07/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188340
Colour:	Blue	Odometer:	144650 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,567.06	1,249.42	317.64	20.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,347.06</b>	<b>1,879.42</b>	<b>467.64</b>	<b>19.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	164.29	131.56	32.73	19.92
<b>Nett Amount (S\$)</b>	<b>2,511.35</b>	<b>2,010.98</b>	<b>500.37</b>	<b>19.92</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$125.19/day) (S\$)</b>		250.38		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,363.36</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,300.00</b>		

INSPECTION

Date of Assignment:	22/11/2021	
Date Inspected:	22/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Torn	459.40 FL	*459.40 FL
2	1		*REAR BUMPER UNDER COVER	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	*- FL
5	1		*REAR FOG LAMP	Cracked	201.50 FL	*201.50 FL
6	1		*ANTENNA -SMARTKEY	Cracked	40.50 FL	*40.50 FL
7	1		*MOULDING REAR BUMPER LOWER	Cracked	155.00 FL	*155.00 FL
8	1		*REVERSE SENSOR	Not Working	137.50 FS	*135.70 FS
9	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
					<b>Sub Total (\$\$)</b>	<b>1,911.95      1,515.35</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>344.89      265.93</b>
					<b>Total Parts (\$\$)</b>	<b>1,567.06      1,249.42</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>780.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >