

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011862/T1TY3N2**Date:** 23/12/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00057352100		
Claimant Vehicle No :	YP5022Z	Insured Vehicle No :	GBL3384K		
Date of Loss:	17/11/2021	Nature of Claim:	TP	Claim No:	SNM21D206647/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP5022Z		Engine No:	4JJ12M8199
Make & Model:	ISUZU NNR85UH4A, 3.0 D (M)		Chassis No:	JAANNR85HG7100061
Reg. Date:	01/12/2016 (Man. Year: 2016)		Odometer:	319907 km
Colour:	White			
Engine Capacity:	2999 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R16	Rear Tyre Size:	195/85R16(D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,625.85	7,703.75	23,922.10	75.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,630.00	2,960.00	5,670.00	65.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,255.85	10,663.75	29,592.10	73.51
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	40,255.85	8,500.00	31,755.85	78.89

INSPECTION

Date of Assignment:	23/11/2021	Asia Motorsports-kaki Bukit (HQ)
Date Inspected:	22/11/2021 Inspected At:	15 KAKI BUKIT ROAD 4 #01-05/53 BARTLEY BIZ CENTRE
Estimated Period of Repair:	9.0 days	Singapore 417808

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 23 Dec 2021)	
Parts:	N/A	ISUZU NNR85UH4A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP5022Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Cracked	1,290.00 FL	*798.00 FL
2	1		*FRONT RIGHT BUMPER BRACKET	Bent	160.00 FL	*160.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	375.00 FL	*- FL
4	1		*FRONT BUMPER RIGHT FOG LAMP COVER	Distorted	192.00 FL	*192.00 FL
5	1		*FRONT PANEL ASSY	Deformed	1,285.00 FL	*928.00 FL
6	1		*FRONT INNER PANEL ASSY	Repair	1,910.00 FL	*- FL
7	1		*FRONT PANEL ISUZU EMBLEM	Necessary	128.00 FL	*128.00 FL
8	1		*FRONT RIGHT CORNER PANEL	Missing	271.00 FL	*271.00 FL
9	1		*FRONT RIGHT INNER CORNER PANEL	Repair	899.00 FL	*- FL
10	1		*FRONT GRILLE ASSY	Cracked	693.00 FL	*575.00 FL
11	1		*FRONT RIGHT HEADLAMP	Cracked	769.00 FL	*510.00 FL
12	1		*FRONT TORSION BAR	Not Necessary	846.00 FL	*- FL
13	2		*FRONT TORSION BAR BUSHING	Not Necessary	185.00 FL	*- FL
14	1		*FRONT RIGHT DOOR SIGNAL LAMP	Cut	92.00 FL	*92.00 FL
15	1		*FRONT RIGHT DOOR PANEL	Bent	1,560.00 FL	*1,287.00 FL
16	1		*FRONT RIGHT DOOR MOULDING	Cut	187.00 FL	*187.00 FL
17	1		*FRONT RIGHT DOOR OUTER HANDLE	Not Necessary	124.00 FL	*- FL
18	2		*FRONT RIGHT DOOR HINGES	Bent	160.00 FL	*160.00 FL
19	1		*FRONT RIGHT DOOR INNER STEP BOARD	Deformed	277.00 FL	*130.00 FL
20	1		*FRONT RIGHT DOOR INNER TRIM BOARD	Cracked	356.00 FL	*288.00 FL
21	1		*FRONT RIGHT DOOR OUTER STEP GARNISH	Missing	267.00 FL	*267.00 FL
22	1		*FRONT RIGHT DOOR STEP REFLECTOR	Not Necessary	68.00 FL	*- FL
23	1		*FRONT RIGHT DOOR LOCK MECHANISM	Not Necessary	162.00 FL	*- FL
24	1		*FRONT RIGHT DOOR CHECKER LINKAGE	Bent	136.00 FL	*136.00 FL
25	1		*FRONT RIGHT DOOR WINDOW REGULATOR	Not Necessary	376.00 FL	*- FL
26	1		*FRONT RIGHT DOOR WINDOW MOTOR	Not Necessary	451.00 FL	*- FL
27	1		*FRONT RIGHT DOOR OUTER MOULDING	Not Necessary	188.00 FL	*- FL
28	1		*FRONT RIGHT DOOR INNER WEATHERSTRIP	Cut	128.00 FL	*128.00 FL
29	1		*FRONT RIGHT DOOR OUTER WEATHERSTRIP	Cut	168.00 FL	*168.00 FL
30	1		*FRONT RIGHT SIDE MIRROR	Missing	653.00 FL	*215.00 FL
31	1		*FRONT RIGHT MUDFLAP	Not Necessary	215.00 FL	*- FL
32	1		*FRONT WIPER TANK	Not Necessary	108.00 FL	*- FL
33	1		*SET FRONT WIPER BLADE ASSY	Cut	140.00 FL	*140.00 FL
34	1		*SET FRONT WIPER SPRAY WASHER NOZZLE	Cut	160.00 FL	*160.00 FL
35	1		*FRONT WIPER INNER PANEL	Repair	650.00 FL	*- FL
36	1		*FRONT WIPER OUTER PANEL	Repair	791.00 FL	*- FL
37	1		*FRONT DASHBOARD ASSY	Not Necessary	2,515.00 FL	*- FL
38	1		*FRONT DASHBOARD GLOVE BOX	Not Necessary	183.00 FL	*- FL
39	1		*FRONT DASHBOARD CENTRE BEAM	Not Necessary	377.00 FL	*- FL
40	1		*FRONT DASHBOARD CENTRE CONSOLE	Not Necessary	512.00 FL	*- FL
41	1		*FRONT WINDSCREEN GLASS ASSY	Cracked	2,670.00 FL	*1,450.00 FL
42	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	388.00 FL	*245.00 FL
43	1		*FRONT RIGHT ANTENNA ASSY	Cut	280.00 FL	*160.00 FL
44	1		*FRONT RIGHT A PILLAR	Repair	798.00 FL	*- FL
45	1		*FRONT RIGHT A PILLAR INNER GARNISH	Not Necessary	185.00 FL	*- FL
46	1		*FRONT STEERING COLUMN ASSY	Not Necessary	3,879.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BRAKE BOOSTER	Not Necessary	1,255.00 FL	*- FL
48	1		*FRONT CLUTCH MASTER PUMP	Not Necessary	255.00 FL	*- FL
49	1		*FRONT RIGHT KNUCKLE ARM	Not Necessary	465.00 FL	*- FL
50	1		*FRONT RIGHT AXLE BEAM	Not Necessary	1,560.00 FL	*- FL
51	1		*FRONT RIGHT TRAILING LINK	Not Necessary	246.00 FL	*- FL
52	1		*FRONT RIGHT ANTI ROLL BAR	Not Necessary	455.00 FL	*- FL
53	1		*FRONT RIGHT WHEEL HUB WITH BEARING	Not Necessary	350.00 FL	*- FL
54	1		*FRONT RIGHT SHOCK ABSORBER ASSY	Not Necessary	650.00 FL	*- FL
55	1		*FRONT RIGHT LEAF SPRING ASSY	Not Necessary	1,567.00 FL	*- FL
56	1		*FRONT RIGHT TIE ROD	Not Necessary	191.00 FL	*- FL
57	1		*FRONT GRILLE CLIPS (6 Pcs)	Necessary	50.00 FS	*20.00 FS
58	12		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
59	1		*FRONT RIGHT DOOR INNER STEP BOARD CLIPS } (6 Pcs)	Necessary	40.00 FS	*30.00 FS
60	8		*FRONT RIGHT DOOR INNER TRIM BOARD CLIPS }	Necessary	40.00 FS	*- FS
61	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
62	1		*FRONT ERP UNIT	Not Necessary	180.00 FS	*- FS
63	1		*FRONT ERP UNIT BRACKET	Necessary	35.00 FS	*35.00 FS
64	1		*FRONT RIGHT TYRE	Not Necessary	350.00 FS	*- FS
65	1		*FRONT RIGHT WHEEL RIM	Not Necessary	650.00 FS	*- FS
66	1		*FRONT NO PLATE	Bent	100.00 FS	*30.00 FS
67	1		*FRONT PANEL REWARD NN STICKER	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	36,906.00	9,020.00
- List Item Discount on L Items 15.00/15.00% (S\$)	5,280.15	1,316.25
Total Parts (S\$)	31,625.85	7,703.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AND FRONT RIGHT AFFECTED AREA AND REPLACE FRONT AND FRONT RIGHT DAMAGED PARTS	New	3,200.00	1,300.00
2	TO PUTTY AND SPRAY PAINTING FRONT AND FRONT RIGHT PORTION	New	3,200.00	1,300.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	30.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AND FRONT RIGHT AFFECTED AREA	New	140.00	50.00
5	TO REMOVE AND INSTALL FRONT RIGHT UNDERCARRIAGE PARTS	New	350.00	0.00
6	TO BALANCE FRONT RIGHT WHEEL	New	50.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	TO REMOVE AND INSTALL FRONT RIGHT WING MIRROR FOR FUNCTION	New	120.00	30.00
9	TO REMOVE AND INSTALL FRONT RIGHT DOOR LOCK MECHANISM	New	80.00	40.00
10	TO CHECK FRONT RIGHT DOOR CENTRAL LOCKING FOR FUNCTION }	New	80.00	30.00
11	TO TRANSFER FRONT RIGHT DOOR GLASS TO NEW DOOR }	New	80.00	0.00
12	TO REMOVE AND INSTALL FRONT RIGHT DOOR REGULATOR WITH MOTOR ASSY }	New	80.00	0.00
13	TO CLEAN AND VACUUM THE GLASS DEBRIS IN THE INTERIOR OF THE CAR	New	80.00	30.00
14	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	120.00
15	TO REMOVE AND INSTALL FRONT BRAKE BOOSTER AND CLUTCH MASTER PUMP	New	300.00	0.00
16	TO REMOVE AND INSTALL FRONT STEERING COLUMN ASSY	New	300.00	0.00
17	TO REMOVE AND INSTALL FRONT VIEW CAMERA	New	80.00	30.00
18	TOWING SERVICE	New	180.00	0.00
			Gross Labour Cost (\$)	8,630.00
				2,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >