



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4159B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BAR HANDLE	BENT	70.50	70.50
1	BOX SIDE (MOTOMALL) ALUMINIUM 38L (MATT BLACK)	SCRATCHED	529.50	529.50
1	BRACKET FOOTREST REAR LH	SERVICEABLE	60.00	-
1	BRACKET IU METER (UNIVERSAL) S/STEEL	BENT	24.00	24.00
1	BRACKET LED XT12 PEDESTAL MOUNT WITH KIT	SERVICEABLE	46.50	-
1	BRACKET SUPPORT CRASH BAR FRONT LH (CISCO)	SCRATCHED	82.50	82.50
1	BRACKET UPPER COWLING FRONT	DENTED	47.00	47.00
1	CAMERA REAR IP68	SCRATCHED	618.00	618.00
1	COVER A FRONT UPPER	SERVICEABLE	53.50	-
1	COVER B FRONT UPPER	SERVICEABLE	53.50	-
1	COWLING FRONT LH	SCRATCHED	363.70	363.70
1	CRASH BAR OUTER LH FRONT WITH SIREN MOUNT (CISCO)	SCRATCHED	288.50	288.50
1	CRASH BAR REAR LH (CISCO)	SCRATCHED	155.00	155.00
1	LAMP SIGNAL FRONT LH	SCRATCHED	103.10	103.10
1	LIGHT LED (JL) 12 LED RED / BLUE WITH CLEAR LENS	SCRATCHED	297.00	297.00
1	METER ASSY	SCRATCHED	424.20	424.20
1	METER IU (12V) NEW MODEL	SCRATCHED	206.00	165.00
1	MIRROR LH	SCRATCHED	86.00	86.00
1	PANEL L.INNER	DISTORTED	20.50	20.50
1	PANEL METER	SCRATCHED	62.50	62.50
2	SCREW PAN @\$4.60	NECESSARY	9.20	9.20
1	STAY COWLING FRONT UPPER	BENT	117.50	117.50
1	STAY SCREEN LH	DENTED	41.50	41.50
1	STAY SCREEN RH	DENTED	41.50	41.50
1	STICKER (CERTIS CISCO) WINDSHIELD	NECESSARY	36.50	36.50
1	STICKER (CISCO) COWLING FRONT LH	NECESSARY	19.50	19.50
1	STICKER (CISCO) COWLING SIDE LH	NECESSARY	32.00	32.00
1	STICKER (LTA) TRAFFIC MARSHALL SIDE BOX LH	NECESSARY	292.50	292.00
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT REPLACE	NECESSARY	20.00	20.00

Report Ref No. CS/FCI21011866/Vvf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSHIELD - CLEAR (PUIG)	CRACKED	222.00	222.00
1	M10 WHEEL WALKER WALKING MEASURE (ADDITIONAL)	DAMAGED	50.00	50.00
			4,473.70	4,218.70
	LABOUR			
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.		630.00	400.00
	SPRAY PAINT ON COWLING FRONT LH.		145.00	130.00
	TRANSPORT CHARGES (MOTORCYCLE) GLASS 2.		110.00	45.00
			885.00	575.00
GRAND TOTAL			5,358.70	4,793.70

RECOMMENDED COST OF REPAIRS			4,793.70
LESS EXCESS			-1,500.00
NETT LIABILITY			3,293.70

Report Ref No. CS/FCI21011866/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.