

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011873/EPA3Q2**Date:** 02/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100451749-05
Claimant Vehicle No :	SMF2085G	Insured Vehicle No :	SKZ9706X
Date of Loss:	21/11/2021	Nature of Claim:	TP
		Claim No:	3573672813SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF2085G	Engine No:	G4FGJH709903
Make & Model:	KIA CERATO, 1.6 LX (A)	Chassis No:	KNAF1416MK5019017
Reg. Date:	31/10/2018 (Man. Year: 2018)	Odometer:	40317 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,089.00	573.60	1,515.40	72.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	2,100.00	360.00	14.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,549.00	2,673.60	1,875.40	41.23
+ GST 7.00/7.00% (S\$)	318.43	187.15	131.28	41.23
Nett Amount (S\$)	4,867.43	2,860.75	2,006.68	41.23
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
		(S\$)		
		3,280.75		
Liabe Amount (86.00%) (S\$)		2,821.45		
+ Doc/Search Fee (S\$)		2.00		
		Nett Liability (S\$)		
		2,823.45		
Global Sum Settlement (S\$)		2,800.00		

INSPECTION

Date of Assignment:	22/11/2021	
Date Inspected:	22/11/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Not Necessary	633.00 FS	*- FS
3	1		*GRILLE -FRONT BUMPER	Cut	262.00 FS	*209.60 FS
4	1		*BRACKET -FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FS	*- FS
5	1		*PANEL-FENDER ,LH	Dented	430.00 FS	*344.00 FS
6	1		*HUB ASSY-FR WHEEL	Not Necessary	436.00 FS	*- FS
7	1		*ARM COMPLETE -FR LWR ,LH	Not Necessary	286.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,089.00	573.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER ,FRT FENDER LH	New	800.00	800.00
2	SPRAY PAINT FOR FRT BUMPER ,FRT FENDER LH	New	700.00	700.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	TRANSFER FRT LEFT RIM	New	30.00	30.00
5	SUPPLY FRT LEFT RIM	New	360.00	300.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	RENEW FRT UNDER CARRIAGE	New	300.00	0.00
Gross Labour Cost (\$\$)			2,460.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >