

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21011875/ETF3E2

**Date:** 05/01/2022

### REFERENCE

Insured/Claimant: NG LI LI Policy No: 2100488430  
Date of Loss: 19/11/2021 Nature of Claim: OD Claim No: 2295646398SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH3332M**  
Make & Model: MITSUBISHI LANCER, 1.3 (A) Engine No: 4A92CL7746  
Reg. Date: 31/10/2016 (Man. Year: 2016) Chassis No: JMYSRCY1AGU005952  
Colour: Silver Odometer: 85994 km  
Engine Capacity: 1590 cc  
Market Value/New Car Price: S\$51,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,752.71	2,628.76	123.95	4.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	2,065.00	675.00	24.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,492.71</b>	<b>4,693.76</b>	<b>798.95</b>	<b>14.55</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>384.49</b>	<b>328.56</b>	<b>55.93</b>	<b>14.55</b>
<b>Nett Amount (S\$)</b>	<b>5,877.20</b>	<b>5,022.32</b>	<b>854.88</b>	<b>14.55</b>

### INSPECTION

Date of Assignment: 23/11/2021

Date Inspected: 06/12/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, LH	Cut	851.00 FL	*851.00 FL
3	1		*WHEEL, DISC	Cut	783.00 FL	*783.00 FL
4	1		*FACE, FR BUMPER	Broken	1,045.00 FL	*1,045.00 FL
5	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
6	1		*BRACKET, FR BUMPER SIDE, LH	Broken	17.00 FL	*17.00 FL
7	1		*BRACKET, FR FENDER, LH	Not Necessary	16.00 FL	*- FL
8	1		*SHIELD, FR FENDER, FR LH	Not Necessary	119.00 FL	*- FL
9	1		*FENDER, FR LH (Supplementary)	Dented	622.00 FL	*622.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,563.00</b>	<b>3,408.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$)</b>	810.29	779.24
<b>Total Parts (\$)</b>	<b>2,752.71</b>	<b>2,628.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER & AFFECTED AREA. REPAIR ON FRT LH FENDER & FRT LH DOOR	New	1,350.00	675.00
2	PAINT WORK ON FRT BUMPER, FRT LH FENDER & FRT LH DOOR	New	1,050.00	1,050.00
3	PERFORM RUST PREVENTION	New	40.00	40.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	TO TRANSFER FRT LH RIM INCLUDING BALANCING	New	30.00	30.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
			<b>Gross Labour Cost (\$)</b>	<b>2,740.00</b>
				<b>2,065.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >