



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Ng Li Li</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLH3332M / 31/10/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>JMYSRCY1AGU005952</td></tr> <tr> <td>Engine No</td><td>4A92CL7746</td></tr> <tr> <td>Make/Model</td><td>MIT/16MY LANCER EX 1.6 4AT</td></tr> <tr> <td>Colour/Trim</td><td>A01 WARM SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Ng Li Li	Reg No/Reg Date	SLH3332M / 31/10/201	Date In/Mileage	/ 0	Chassis No	JMYSRCY1AGU005952	Engine No	4A92CL7746	Make/Model	MIT/16MY LANCER EX 1.6 4AT	Colour/Trim	A01 WARM SILVER MET/ BK BLACK
Cust No/Name	/Ng Li Li														
Reg No/Reg Date	SLH3332M / 31/10/201														
Date In/Mileage	/ 0														
Chassis No	JMYSRCY1AGU005952														
Engine No	4A92CL7746														
Make/Model	MIT/16MY LANCER EX 1.6 4AT														
Colour/Trim	A01 WARM SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/11/2021/ 10:19	BLK	282 / Kevin Leong	17778		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER & AFFECTED AREA REPAIR ON FRT LH FENDER & FRT LH DOOR				450 x 1.5			675 1350.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT LH FENDER & FRT LH DOOR				3 x 350			1050.00
M SUNDRY PERFORM RUST PREVENTION							40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M SUNDRY TO TRANSFER FRT LH RIM INCLUDING BALANCING							30.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY SUNDRIES							20 40.00
M HEADLAMP ASSY, LH				1.00	851.00	23.00	655.27
M WHEEL, DISC				1.00	783.00	23.00	602.91
M FACE, FR BUMPER				1.00	1045.00	23.00	804.65
M MARK, THREE-DIA				1.00	70.00	23.00	53.90
M BRACKET, FR BUMPER SIDE, LH				1.00	17.00	23.00	13.09
M BRACKET, FR FENDER, LH				1.00	16.00	23.00	12.32
M SHIELD, FR FENDER, FR LH				1.00	119.00	23.00	91.63

Estimate

Steve CLKK)
6/12/21, 1.39p-

OP- NA 10
EXCISE - ?
PIP
My Re L
5 days

LKK Auto Consultants hence notify
the Receiver of the following

Estimate

Steve CLKK
6/12/21, 1.39p00-NA 14
EXCISE - ?
PIP
My Re L
5 dyl

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (time/s) must be resurveyed and is subject to final approval from the Insurer Company

Authorized signatory and company stamp

7% GST on	Nett	5,013.77
	5013.77	350.96
Total Payable		5,364.73

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.