



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Ng Li Li
	Reg No/Reg Date	SLH3332M / 31/10/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AGU005952
	Engine No	4A92CL7746
	Make/Model	MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim	A01 WARM SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/11/2021/ 10:19	BLK	282 / Kevin Leong	17778			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1350.00
REPLACE FRT BUMPER & AFFECTED AREA								
REPAIR ON FRT LH FENDER & FRT LH DOOR								
E PNT98000								1050.00
PAINT WORK ON FRT BUMPER, FRT LH FENDER & FRT LH DOOR								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								30.00
TO TRANSFER FRT LH RIM INCLUDING BALANCING								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								40.00
SUNDRIES								
M	HEADLAMP ASSY,LH				1.00	851.00	23.00	655.27
M	WHEEL,DISC				1.00	783.00	23.00	602.91
M	FACE,FR BUMPER				1.00	1045.00	23.00	804.65
M	MARK,THREE-DIA				1.00	70.00	23.00	53.90
M	BRACKET,FR BUMPER SIDE,LH				1.00	17.00	23.00	13.09
M	BRACKET,FR FENDER,LH				1.00	16.00	23.00	12.32
M	SHIELD,FR FENDER,FR LH				1.00	119.00	23.00	91.63

Confirm & accepted by

7% GST on **Nett** **5,013.77**
 5013.77 **350.96**
Total Payable **5,364.73**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.