

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21011876/EQF3E2

Date: 06/01/2022

REFERENCE

Insured/Claimant: JOANNE TAN JONG HENG (CHEN RONGTING) Policy No: 1800128102-02
Date of Loss: 19/11/2021 Nature of Claim: OD Claim No: 8699788432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF2257C**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH709009
Reg. Date: 31/10/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5019831
Colour: Blue Odometer: 0 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$64,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,230.00	7,957.60	272.40	3.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,310.00	5,830.00	1,480.00	20.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,540.00	13,787.60	1,752.40	11.28
+ GST 7.00/7.00% (S\$)	1,087.80	965.13	122.67	11.28
Nett Amount (S\$)	16,627.80	14,752.73	1,875.07	11.28

INSPECTION

Date of Assignment: 23/11/2021
Date Inspected: 23/11/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 13.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-REAR COMB INSIDE, LH	Cut	608.00 FL	*608.00 FL
3	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cut	608.00 FL	*608.00 FL
4	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Cut	675.00 FL	*675.00 FL
5	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 FL	*675.00 FL
6	1		*LAMP ASSY-CENTER GARNISH	Broken	690.00 FL	*690.00 FL
7	1		*MUFFLER ASSY-REAR	Cut	757.00 FL	*757.00 FL
8	1		*GASKET-EXHAUST PIPE	Not Necessary	14.00 FL	*- FL
9	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
10	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
11	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
12	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
13	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
14	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
15	1		*COVER-RR BUMPER UNDER, LH	Broken	33.00 FL	*33.00 FL
16	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	88.00 FL	*88.00 FL
17	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	88.00 FL	*88.00 FL
18	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Cut	181.00 FL	*181.00 FL
19	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
20	1		*EXTN WIRING ASSY-BWS	Broken	207.00 FL	*207.00 FL
21	1		*BRACKET-RR BEAM UPR MTG, LH	Broken	9.00 FL	*9.00 FL
22	1		*BRACKET-RR BEAM UPR MTG, RH	Broken	9.00 FL	*9.00 FL
23	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 FL	*6.00 FL
24	1		*BRACKET-RR BEAM LWR MTG (2PCS)	Broken (1Pc Only)	12.00 FL	*6.00 FL
25	1		*BEAN-RR BUMPER	Broken	318.00 FL	*318.00 FL
26	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
27	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
28	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
29	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
30	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
31	1		*ULTRASONIC SENSOR ASSY-BWS	Shorted	163.00 FL	*163.00 FL
32	1		*ULTRASONIC SENSOR ASSY-BWS	Shorted	163.00 FL	*163.00 FL
33	1		*ULTRASONIC SENSOR ASSY-BWS	Shorted	163.00 FL	*163.00 FL
34	1		*TRIM ASSY-RR TRANSVERSE (Supplementary)	Crushed	41.00 FL	*41.00 FL
35	1		*MAT ASSY-LUGGAGE COVERING (Supplementary)	Torn	211.00 FL	*211.00 FL
36	1		*CLAMP-SPARE TIRE (Supplementary)	Broken	6.00 FL	*6.00 FL
37	1		*LATCH ASSY-TRUNK LID (Supplementary)	Bent	112.00 FL	*112.00 FL
38	1		*TRIM ASSY-TRUNK LID (Supplementary)	Crushed	202.00 FL	*202.00 FL
39	10		*FASTENER (Supplementary)	Necessary	10.00 FL	*10.00 FL
40	1		*PROTECTOR-HEAT REAR (Supplementary)	Bent	136.00 FL	*136.00 FL
41	15		*CLIP (Supplementary)	Necessary	15.00 FL	*15.00 FL
42	1		*SILENCER, FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
43	1		*W/STRIP-TRUNK LID OPNG (Supplementary)	Crushed	100.00 FL	*100.00 FL
44	1		*WHEEL ASSY-ALUMINIUM (Supplementary)	Cut	926.00 FL	*926.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,275.00	9,942.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,045.00	1,984.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,230.00
						7,957.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, END PANEL, BOOT & AFFECTED AREA. REPAIR ON FLOOR PANEL & REAR LH FENDER	New	2,400.00	1,800.00
2	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, REAR LH FENDER & FLOOR PANEL	New	1,750.00	1,400.00
3	REMOVE & REPLACE REAR PARKING ASSIST	New	120.00	80.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
5	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	120.00	120.00
6	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	80.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
10	TO SUPPLY C & C EMBLEM	New	40.00	40.00
11	TO SUPPLY REAR NUMBER PLATE WITH FRAME	New	50.00	0.00
12	REPLACE REAR EXHAUST MUFFLER	New	400.00	0.00
13	MOUNTED ONTO FLOOR BENCH TO FACILITATE REPAIR (Supplementary)	New	500.00	500.00
14	REPAIR FLOOR PANEL & RH REAR FENDER (Supplementary)	New	800.00	800.00
15	SPRAY PAINT FLOOR PANEL & RH REAR FENDER (Supplementary)	New	700.00	700.00
Gross Labour Cost (S\$)			7,310.00	5,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >